



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79060
Promised Date:

CUSTOMER WORK ORDER

WO #: 79060

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: BH
Location: 0304 CHECK WORK

Stock #: 11718
Stock Desc: 2026 TT COACHMEN
CATALINA SUMMIT 164BHX
Chassis #: 5ZT2CAEC6TK014307
Serial #: 5ZT2CAEC6TK014307
Mileage: 0
Licence:

Invoice #:
Date In: 19 FEB 26
Promised: 28 FEB 26
Date Sched:
Completed: 28 FEB 26
Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Brought unit in. Torqued lugnuts to 110ftlbs. Aired tires to 65psi. Checked breaks and ebreaks on unit to be working. All clearnace lights are working and break lights. Awning works running in and out and awning lights work. Range works. Furance works microwave works, water heater works. All water points work on city. All interior and exterior lights work. All cabinets open and close propely. Smoke detector and C02 detector work. Fridge works. Ac unit works on cool and heat pump. All outlets work. Used test tv and picture and sound came through. Ran lp drop test at 13.5 starting pressure. Unit held 8wic for 5mins. All windows open and close properly. Cap lights work. All 12v systems work. Tanks sensors work on reading levels in tank. Water pump works. Added cable to tv in unit. Tested tv with nrw cable and sound and picture comes through. Exterior metal looks good. Stabilzer jacks work.

Customer #: 1000
BASDENS AMERICAN RV,



Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Went to unit and found water pump. Set to winterize and connected to antifreeze. Ran pink on hot and cold to kitchen sink and shower. Ran pink to toilet. Depressed water heater and city connection. Drained fresh, grey, and black tanks





Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	CCV	N/C
Z990	WINTERIZE UNIT	CCV	N/C
Z990	WINTERIZE UNIT	CCV	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: ONE LIGHTS ON THE NOSE CAP ARE NOT SECURED PROPERLY.

CAUSE: Cap lights

CORRECTION: During pdi noticed cap light were not secure at top of unit. Webt to roof and pulled lights back and secured with dicor

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Subtotal for Job #1: 37.00

Job #2 - Warranty

COMPLAINT: THERE IS A SCRATCH ON THE CABINET ABOVE THE DINNETTE

CAUSE: Scartch on cabinet above dinette

CORRECTION: During pdi notciied a scratch on wood above dinette. Grabbed white putty and black and blended unit grey color was achieved. Placed in scratch and added white on top of grey to blend into wood.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50

Subtotal for Job #2: 55.50

Job #3 - Warranty

COMPLAINT: THERE IS A SCRATCH ON THE DINNETE FABRIC

CAUSE: Dinette fabric

CORRECTION: During pdi noticed the fabric on the dinette had a scratch and been torn . Pictures taken. Parts request submitted

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Sublet

Description	Total
FIX VINYL ON DINETTE	250.00



Subtotal for Job #3: 250.00

Job #4 - Warranty

COMPLAINT: THA WATER PUMP DOES NOT HOLD PRESSURE

CAUSE: Water pump

CORRECTION: During pdi while trying to run water pump it would surge instead of holding pressure. Checked quick connects on power supply to be holding. Parts request submitted for new water pump. Recieved new pump removed old pump from water lines. Removed wiring from old pump. Removed screws holding pump in place and pulled off unit. Added filter to new pump and wired new pump in. Placed in hole and connected water lines. Test new pump to make sure it works. New pump works. Secured pump in place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
333426	Pump - Water - Revolution - 12V - 3	1.00	57.28	57.28

Subtotal for Job #4: 149.78

Job #5 - Warranty

COMPLAINT: DECALS ARE BUBBLEING

CAUSE: Bubbles in decal

CORRECTION: Went to unit and saw multiple bubbles in decal. Had to releave 4 decals with 10-20 bubbles in each

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	22.20
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	24.05

Subtotal for Job #5: 46.25

Job #6 - Warranty

COMPLAINT: SCRATCH ON DECAL

CAUSE: Decals

CORRECTION: During pdi noticed 3 decals had scratches, cuts, or foreign objects under decal. Pictures taken. Parts request submitted

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	222.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
F100418578	GRAPHIC, #13 DS "CATALINA" LOGO 202	1.00	11.54	11.54
11022	GRAPHIC, #5A SIDE MID LWR BLK D/C DS	1.00	13.75	13.75
F100748554	GRAPHIC, #33 REAR DIG SUMMIT SERIES	1.00	6.89	6.89

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-GRAPHICS	1.00	16.30	16.30

W/O: 79060
Promised Date: 28 FEB 26



Customer #: 1000
BASDENS AMERICAN RV,



Subtotal for Job #6: 270.48

Parts Total:	89.46
Labour Total:	453.25
Sublet Total:	250.00
Extras Total:	16.30
WORK ORDER TOTAL:	809.01

W/O: 79060
Promised Date: 28 FEB 26

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Mar 2026



Customer Work Order

Customer #: 1000
BASDENS AMERICAN RV,

