



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79061
Promised Date:
06 FEB 26



CUSTOMER WORK ORDER

WO #: 79061

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0306 SEE IF BB HAS
BROUGHT THIS IN YET

Stock #: 11719
Stock Desc: 2026 TT COACHMEN
CATALINA SUMMIT 134RDX
Chassis #: 5ZT2CABC4TK014343
Serial #: 5ZT2CABC4TK014343
Mileage: 0
Licence:

Invoice #:
Date In: 19 FEB 26
Promised: 28 FEB 26
Date Sched:
Completed: 06 MAR 26
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*79183 on 05 MAR 26
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery box. Filled 1 20# lp tank. Exterior inspection entry door needs adjusted. Grey tank sticker torn. And a dent in metal off door side front behind running light. Roof inspection found void in the black dicor on door side front. And both sides at the top of cap light hav gaps. Other than that roof looks good. Awning fabric and hardware looks and works properly Awning lights work properly Interior inspection hooked up to city water and flushed out all the lines. Stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly water heater works properly lp-co detector works properly smoke alarm works properly made a antenna cable for tv. All the outlets work properly all but one usb ports work properly the one by table has no power antenna works properly. Water pump works properly

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*79183 on 05 MAR 26
Estimate amount was 0.00
WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Turned valve to winterize and pumped winterize solution through the water pump to bathroom shower cold and hot until solution was there then repeated for toilet and kitchen faucet. Drained



Customer #: 1000
BASDEN'S AMERICAN RV,



water heater and depressed city water inlet. Used 2 gallons

Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: DICOR ON ROOF IS GAPPING OPEN

CAUSE: Void in the black dicor

CORRECTION: Cleaned area and put black dicor non sag in the void and touched both sides by light strip

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00

Subtotal for Job #1: 37.00

Job #3 - Warranty

COMPLAINT: ENTRY DOOR CATCHES ON STRIKER AND NOT CLOSING PROPERLY

CAUSE: Entry door hard to open

CORRECTION: Had to adjust the screen door latch because it was dragging on the striker when opening the door and i adjusted the hinges on the main entry door. Door works properly now

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Subtotal for Job #3: 55.50

Job #4 - Warranty

COMPLAINT: OFF DOOR SIDE FRONT HAS DENT IN METAL

CAUSE: Metal has a dent

CORRECTION: Noticed it on the exterior inspection

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	370.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	370.00

Parts				
Part #	Description	Qty	Price	Total
12151	METAL, .024 X 12 X 156 1MDM SL MET S	1.00	40.05	40.05

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-METAL	1.00	559.96	559.96

Subtotal for Job #4: 1,525.01

Job #5 - Warranty

COMPLAINT: USB PORT DIRECTLY INSIDE ENTRY DOOR HAS NO POWER

W/O: 79061
Promised Date: 28 FEB 26

Customer #: 1000
BASDENS AMERICAN RV,

CAUSE: USB port no power

CORRECTION: Took usb port out of the wall and the wire were pulled out of the connector. So i put a new connector on it and the usb port works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	27.75

Subtotal for Job #5: 27.75

Parts Total: 40.05
Labour Total: 1,045.25
Sublet Total: 0.00
Extras Total: 559.96

WORK ORDER TOTAL: 1,645.26

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Mar 2026

W/O: 79061
Promised Date: 28 FEB 26



Customer #: 1000
BASDEN'S AMERICAN RV,

