



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79062



CUSTOMER WORK ORDER

WO #: 79062

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0305 CHECK PREAUTH

Stock #: 11716
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE WOLF PUP 17JW
Chassis #: 5ZT2CKFC3TY041823
Serial #: 5ZT2CKFC3TY041823
Mileage: 0
Licence:

Invoice #:
Date In: 19 FEB 26
Promised:
Date Sched:
Completed: 28 FEB 26
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: Pulled unit into shop and hooked up to shore power. Checked all appliances checked water and electrical systems checked roof and antenna function installed battery box. Filled l.p tanks and ran l.p drop test. Checked doors drawers and cabinets. Checked tire pressure and torqued lugs.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize

CORRECTION: Ran a.f through all lines and fixtures. Drained all tanks and relieved pressure from the water heater.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: GLUE ON KITCHEN TABLE

CAUSE: Glue on the table top.

CORRECTION: Removed glue with mineral spirits and a rag.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	18.50

Subtotal for Job #1: 18.50

Job #2 - Warranty

COMPLAINT: OUTDOOR FRIDGE COMPARTMENT DOOR IS HITTING FRAME

CAUSE: The door is hitting the top of the frame.

CORRECTION: Took a block of wood and a hammer and pushed the frame up away from the door.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	18.50

Subtotal for Job #2: 18.50

Job #3 - Warranty

COMPLAINT: FRONT COMPARTMENT DOOR IS BENT

CAUSE: The compartment door is bent outwards.

CORRECTION: Pushed back in with a hammer.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	18.50

Subtotal for Job #3: 18.50

Job #4 - Warranty

COMPLAINT: THE DICOR WAS WET WHEN THE UNIT WAS DELIVERED AND HAS RIPPLED

CAUSE: Roof needs dicor applied over the voids

CORRECTION: Applied dicor to the roof as needed.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	4.00	8.72	34.88

Subtotal for Job #4: 71.88

Job #5 - Internal

COMPLAINT: BOTH FRONT AND REAR STAY JACKS NOT WORKING

Customer #: 1000
BASDENS AMERICAN RV,



CAUSE: I have no power going to the stab jacks.

CORRECTION: Found the battery disconnect is on. Turned the disconnect off and i now have power to the jacks.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Subtotal for Job #5:			0.00

Parts Total: 34.88
Labour Total: 92.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 127.38

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Mar 2026

W/O: 79062



Customer #: 1000
BASDENS AMERICAN RV,

