



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79088
Promised Date:
24 MAR 26

CUSTOMER WORK ORDER

WO #: 79088

Customer: 56525 - LUPFER, BRIDGET -
812-319-6084

Tag:

Author: PH

Location: DELIVERY 0228

Stock #: 11493

Stock Desc: 2025 TT COACHMEN APEX
188RBST

Chassis #: 5ZT2CXHB7SS048163

Serial #: 5ZT2CXHB7SS048163

Mileage:

Licence:

Invoice #:

Date In: 23 FEB 26

Promised: 31 MAR 26

Date Sched:

Completed: 28 FEB 26

Warr. Date: 28 FEB 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi.

CORRECTION: Brought unit in. Unit was missing battery box. Added battery box and put drain holes in box. Placed new battery in unit. Checked breaks and ebreaks to be working. Torqued lugnuts to 110ftlbs. Aired all tires to 65psi including spare. Checked all clearnace and break lights to be working. Went to roof and found no cracks or voids on roof. Went inside after turn lp on and tested water heater, furance, and range to be working. All outlets work. Ac unit works. Interior lights work. Microwave works. Range fan and lights work. Outdoor stove works. Ran lp drop test. Unit passed. Ran leak test at 8iwc for 5mins. Unit passed. Fridge works on unit. Tv and antenna works on unit. Control board works on unit. Water pump works. Kmife valves on grey and black tank work. Sensors work on all tanks. Compartment doors lock and open properly. Tougne jack works. Stablizer jack works. Battery disconnect works. Interior of unit is in goor condition free of scratches in wood or tears in fabric. All cabinets and drawers work properly. Folding table in unitnfree of dents or scratches. All windows open and close properly and blinds work correctly. Bathroom vent fan opens and closes and runs well. Step adjustments work. Entry door latches properly. Walked around exterior of unit and did not see cracks or voids in seals. All decals are in good condition. Water pump works at all water points

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	CCV	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	CCV	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #SWAP - Internal

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CAUSE: Swap hitch

CORRECTION: Swapped hitch

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C



Customer #: 56525
LUPFER, BRIDGET



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Internal

COMPLAINT: SWAP CAMERA FROM TRADE - TRADE WILL BE HERE FRIDAY

CAUSE: Swap camera from trade in to new unit

CORRECTION: Swapped camera from trade in to new unit

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #1: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize

CORRECTION: Went to unit. Left tankless water heater on. Found pump and set lines to winterize. Ran pink on hot and cold to kitchen sink, bathroom sink, shower, and outdoor shower. Ran pink to toilet. Depressed water heater and city connection. Drained fresh, grey, and black tank. Used two gallons of antifreeze. Cleanwd up pink at water points.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #2 - Warranty

COMPLAINT: THE CITY WATER INLET PORT LEAKS

CAUSE: City water inlet

CORRECTION: During pdi noticed the city water inlet has blown. While running unit from fresh tank on pump saw city connection was leaking water parts request submitted. Recieved new inlet. Went to unit and removed screws from inlet. Disconnected inlet from water line and placed new one on. Place putty tape on back of inlet and screwed into place. Once in placed tested inlet by turning on water pump. Inlet no longer leaks with pump on

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



94215 CITY WATER FILL W/BRASS CHECK VALVE, 1.00 17.25 17.25

Subtotal for Job #2: 72.75

Job #3 - Internal

COMPLAINT: SWAP CAMERA

CAUSE: Camera swap

CORRECTION: Removed camera from a Coleman Love Shack trade in and installed it on customer new unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

COMPLAINT: INSTALL OUTSIDE TV MOUNT

CAUSE: Mount outside tv mount

CORRECTION: Mounted outside tv mount in customer desired spot

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
30I48989A	1-SET TV, BRACKET FOR 19" TV - BLACK	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Job #5 - Internal

SPEAKER FOR CUSTOMER

Parts

Part #	Description	Qty	Price	Total
F100411771	SPEAKER, BLUETOOTH EEVD-08 W/ CHARGE	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SPEAKER	1.00	N/C	N/C

Subtotal for Job #5: 0.00

Parts Total: 17.25
Labour Total: 55.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 72.75

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 79088
Promised Date: 31 MAR 26



Customer #: 56525
LUPFER, BRIDGET



Customer Signature : _____

Date: 05 Mar 2026

W/O: 79088
Promised Date: 31 MAR 26



Customer #: 56525
LUPFER, BRIDGET



Customer Work Order

