



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79098
Promised Date:



CUSTOMER WORK ORDER

WO #: 79098

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0310 CHECK STATUS WITH
ZMS

Stock #: 11721
Stock Desc: 2026 5W KEYSTONE
COUGAR HALF-TON 28RLI
Chassis #: 4YDFCGN27T2505074
Serial #: 4YDFCGN27T2505074
Mileage: 0
Licence:

Invoice #:
Date In: 23 FEB 26
Promised: 28 FEB 26
Date Sched:
Completed: 12 MAR 26
Warr. Date:

Job #PDINFW - Internal

COMPLAINT: Transferred to BAS*79182 on 05 MAR 26

Estimate amount was 0.00

PDI - NEW FIFTH WHEEL

CAUSE: Pdi

CORRECTION: Pulled unit into shop and hooked up to shore power. Checked all appliances checked water and electrical systems checked roof and antenna function installed battery box. Filled l.p tanks and ran l.p drop test. Checked doors drawers and cabinets. Checked tire pressure and torqued lug nuts. Documented model and serial numbers.

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*79182 on 05 MAR 26

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize

CORRECTION: Ran a.f through all lines and fixtures. Drained all tanks. Released pressure relief valve on the water heater.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C

Customer #: 1000
BASDEN'S AMERICAN RV,





Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: THERE ARE GROOVES ON THE KITCHEN TABLE.

CAUSE: There are several grooves on the table.
 Table

CORRECTION: Removed nuts on damaged table. Put table on saw horses. Un screwed metal plate. Put metal plate on new table. Put new table back on.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	36.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
758911	TABLE-TOP ONLY - 27.5 x 39" COCOA OA	1.00	207.48	207.48

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT - TABLE	1.00	162.83	162.83

Subtotal for Job #1: 406.31

Job #2 - Warranty

COMPLAINT: THE PANEL IS LOOSE ABOVE THE REFRIGERATOR.

CAUSE: Thr trim popped loose on the facia.

CORRECTION: Secured trim with Brad nails.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	18.00

Subtotal for Job #2: 18.00

Job #3 - Warranty

COMPLAINT: THE PANEL ABOVE THE RECLINERS IS LOOSE

CAUSE: The trim popped loose on the facia board.

CORRECTION: Secured panel with Brad nails.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	36.00

Subtotal for Job #3: 36.00



Parts Total: 207.48
Labour Total: 90.00
Sublet Total: 0.00
Extras Total: 162.83
WORK ORDER TOTAL: 460.31

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 12 Mar 2026

Customer Work
Order

W/O: 79098
Promised Date: 28 FEB 26



Customer #: 1000
BASDENS AMERICAN RV,

