



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79315
Promised Date:
24 MAR 26



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 79315

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0325 BH TO CLOSE

Stock #: 11733

Stock Desc: 2026 TT FOREST RIVER

CHEROKEE GREY WOLF 24RRT

Chassis #: 4X4TCKZ28TK099691

Serial #: 4X4TCKZ28TK099691

Mileage: 0

Licence:

Invoice #:

Date In: 20 MAR 26

Promised: 31 MAR 26

Date Sched:

Completed: 25 MAR 26

Warr. Date:

Job #CHECKTT - Internal

COMPLAINT: CHECK IN NEW TRAVEL TRAILER

CAUSE: Check in

CORRECTION: Preformed check in and filled out Paperwork

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Subtotal for Job #CHECKTT:			0.00

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: Pulled unit into shop and hooked up to shore power. Checked all appliances checked water and electrical systems checked roof and antenna function installed battery box. Filled l.p tanks and ran l.p drop test. Checked doors drawers and cabinets. Checked tire pressure and torqued lug nuts. Documented model and serial numbers.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)		N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00





Job #1 - Warranty

COMPLAINT: PANTRY DOOR IS RUBBING THE FRAME

CAUSE: Door is hitting the frame.

CORRECTION: Took a screw and secured it to the top of the frame to pull it away from the door.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	39.00

Subtotal for Job #1: 39.00

Job #2 - Warranty

COMPLAINT: TOUCH UP DIECOR

CAUSE: The dicor has gaps that need filled.

CORRECTION: Applied dicor to the roof as needed.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	39.00

Parts

Part #	Description	Qty	Price	Total
13-1287	NON SELF LEVELING DICOR	1.00	10.05	10.05

Subtotal for Job #2: 49.05

Parts Total: 10.05
 Labour Total: 78.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 88.05

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 Mar 2026

