



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79325
Promised Date:
21 MAR 26



Customer #: 56540
FISCHER, SARAH



CUSTOMER WORK ORDER

WO #: 79325

Customer: 56540 - FISCHER, SARAH -
812-550-5670

Tag:

Author: BH

Location: 0325 ZBACK IN BRETT'S BOX
TO GET NOTES AND PHOTOS TO FIX

Stock #: 11559

Stock Desc: 2025 TT COACHMEN

FREEDOM EXPRESS 21SE

Chassis #: 5ZT2FEKB7SW030811

Serial #: 5ZT2FEKB7SW030811

Mileage:

Licence:

Invoice #: 427854

Date In: 23 MAR 26

Promised: 31 MAR 26

Date Sched:

Completed: 25 MAR 26

Warr. Date: 06 MAR 26

Job #1 - Warranty

COMPLAINT: THE STABILIZER JACKS - BACK ONE BOLT RUSTED OFF AND WONT STAY UP, AND
ANOTHER ONE THE ARM IS BENT

CAUSE: ONE IS DAMAGED AND THE OTHER IS BENT

CORRECTION: REMOVE THE BROKEN AND BENT JACK AND INSTALL NEW

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	78.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00

Parts

Part #	Description	Qty	Price	Total
285326	24IN SCISSOR JACK KIT WITH CRANK HAN	1.00	122.75	122.75

Subtotal for Job #1: 200.75

Job #2 - Internal

COMPLAINT: THERES A SCREW THAT BROKE OFF THE FRONT LEFT BOTTOM OF THE OUTSIDE
KITCHEN

CAUSE: Missing screw

CORRECTION: Put in new black screw

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE LATCH TO MOVE THE TABLE OF THE DINETTE FELL OFF

CAUSE: LATCH JUST HANGING

CORRECTION: Screwed latch back on. Tested

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	19.50



Subtotal for Job #3: 19.50

Job #4 - Internal

COMPLAINT: THE DOG LEASH HOLDER IS ALSO RUSTED

CAUSE: Dog leash

CORRECTION: Removed dog leash holder and installed new one.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		BB	N/C

Parts				
Part #	Description	Qty	Price	Total
285326	24IN SCISSOR JACK KIT WITH CRANK HANDLE (PAIR)	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Job #5 - External

COMPLAINT: CONVERT LP TANKS FROM 20LB TO 30LB. CUSTOMER SUPPLIED HIS OWN TANKS. HE WANTS TO KEEP HIS 20LB TANKS

CAUSE: Lp cover

CORRECTION: Put together 30 gallon black lp cover. Cut and put new rod on.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		BB	N/C

Parts				
Part #	Description	Qty	Price	Total
06-0344	40539 BLK 30# DBLE TANK COVER	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #5: 0.00

Job #LP - External

COMPLAINT: FILL THE 30LB LB TANKS

CAUSE: Tanks

CORRECTION: Filled two 30 gallon lp tanks

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		BB	N/C

Other Services				
Code	Description	Qty	Price	Total
LPG	LP GAS	0.00	N/C	N/C
LP30	30LB. LP CYLINDER FILL	1.00	N/C	N/C

Subtotal for Job #LP: 0.00

W/O: 79325
Promised Date: 31 MAR 26



Customer #: 56540
FISCHER, SARAH



Parts Total:	122.75
Labour Total:	97.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	220.25

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 26 Mar 2026

Customer Signature : _____

Customer Work
Order

W/O: 79325
Promised Date: 31 MAR 26



Customer #: 56540
FISCHER, SARAH

