



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 63344
Promised Date: 28 FEB 21



Customer #: 50893
REED, BRANDON



CUSTOMER WORK ORDER

WO #: 63344
Customer: 50893 - REED, BRANDON -
812-470-1693
Tag:
Author: BJW
Location: 0219 GET WITH EF TO SEE IF
HE HAS GOTTEN AUTH YET

Stock #: 10656
Stock Desc: 2021 TT COACHMEN
CATALINA 323BHDSCLE
Chassis #: 5ZT2CAXB5MX020687
Serial #: 5ZT2CAXB5MX020687
Mileage:
Licence:

Invoice #:
Date In: 06 FEB 21
Promised: 28 FEB 21
Date Sched:
Completed: 19 FEB 21
Warr. Date: 18 FEB 21

Job #1 - Warranty

COMPLAINT: BUNK ROOM DOOR IS WARPED AND RUBBING
THE WALL...NOTED ON DELIVERY. SWAP PER KW

CAUSE: BUNK DOOR WARPED

CORRECTION: SWAPED DOOR WITH ANOTHER TRAILER ADJUSTED DOOR

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	133.90

Parts Part #	Description	Qty	Price	Total
F100143795	DOOR SLIDER 1-3/8	1.00	45.02	45.02

Other Services Code	Description	Qty	Price	Total
FRT	CRATE FEE	1.00	35.00	35.00
FRT	FREIGHT	1.00	66.55	66.55

Subtotal for Job #1: 280.47

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPD

CORRECTION: FPDINTT

Labor Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	GWG	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	GWG	N/C

Parts Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 D	1.00	N/C	N/C
10268	55185 30M-50F PARK ADAPTER	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #2 - Internal

COMPLAINT: SWAP MATTRESS

CORRECTION: SWAP

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Subtotal for Job #2:			0.00

Job #SWAP - Internal

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CORRECTION: REMOVED CUSTOMERS HITCH WORK, CUSTOMER SWITCH TO EQUALIZER.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	N/C
Subtotal for Job #SWAP:			0.00

Job #WALK - Internal

COMPLAINT: WALK THRU

CAUSE: WALK - WALK THRU.

CORRECTION: Performed walk thru. Showed customer how to hook up new hitch.

Estimated Amount: 180.00

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Subtotal for Job #WALK:			0.00

Job #EQUALIZER1000 - Internal

COMPLAINT: INSTALL 1000# EQUALIZER HITCH

CAUSE: EQ

CORRECTION: INSTALL AND SET UP HITCH

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	N/C

Parts Part #	Description	Qty	Price	Total
710831	EQUALIZER 1000#/10	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #EQUALIZER1000: 0.00

Job #3 - Internal

COMPLAINT: CHAIRS FOR CUSTOMER KEITH
PROMISED...BILL TO SALES PER CHAD

CORRECTION: GAVE CHAIRS

Parts Part #	Description	Qty	Price	Total
37519	ROYAL POD ROCKER W	2.00	N/C	N/C
Subtotal for Job #3:				0.00



Parts Total:	45.02
Labour Total:	133.90
Sublet Total:	0.00
Extras Total:	101.55
WORK ORDER TOTAL:	280.47

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 Apr 2021

Customer Work
Order

