

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 63511

Completed : 18 MAR 21 Customer : 50948 - BRADLEY, JR, DONALD H. - 27
Licence # : Invoice # :
Stock No : 10661 Description : 2021 TT RIVERSIDE RV INTREPID 260RB
Tag : Date In : 04 MAR 21 Mileage : 0
Author : BH Promised : 09 MAR 21
Location : 0309 DELIVERY Date Sched :
Serial# : 59CCC2923ML003790 Chassis# : 59CCC2923ML003790
Warr. Date : 09 MAR 21 Cust PO# :
Print Date : 18 MAR 21

Job # Description JOB INFORMATION Type Bill To

PDIN PDI - NEW TRAVEL TRAILER I PDI PRE-D

FPDI COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS I PDI PRE-D

CORRECTION: install battery, drain water tanks,
reset bypass valves, blow out water
lines, pump in antifreeze, 2 gallons,

1 COMPLAINT: INSTALL SHOWER DOOR 10-2067 I DO DEALE

CORRECTION: walls not square, push pins holding
shower in way to install door, remove
push pins, have to retape shower wall to
wall factory 2 sided tape not holding,
cut tracks to fit 1 wall is 1/4 in out
of square other end is 1/8 in, install
door track and door, seal inside with
clear silacone, seal out side with white
silacone,

SWAP SWAP CUSTOMER'S HITCHWORK I DO DEALE

WALK COMPLAINT: WALK THRU I PDI PRE-D

CORRECTION: DONE EF

2 COMPLAINT: BRAKES INOP ON BRAKE AWAY AND 7WAY W 49672 RIVER

PICTURES ON ONE DRIVE
CORRECTION: JACK UP UNIT AND TEST BRAKES, NO POWER
FROM 7 WAY OR BREAKAWAY, START AT WIRE
CONETION BOX FOR 7 WAY, FOUND GROUND
WIRE TO BREAKS CONETED TO HOT POST IN
BOX, MOVE WIRE TO GROUND POST AND
RETEST, NOW GETTING POWER TO WIRES BUT
BRAKES NOT WORKING, MOVE TO LEFT FRONT
AXEL TO TEST WIRES, FOUND 1 WIRE LOOSE
AT AXEL CONCTION, REMOVE LEFT FRONT TIRE
TO GAIN ACSESS TO WIRES, RECONNET WIRE
AND TEST

3 COMPLAINT: HOLE FOR GAS LINE BEHIND REFER IS OPEN W 49672 RIVER

PICTURES ON ONE DRIVE
CORRECTION: GET SHEET METAL AND CUT TOO FIT, USE
SILACON TO SEAL DOWN, SCREW METAL DOWN,
AND RUN SILACON OVER EDGES AND SCREWS (

Continued on page 2

Work Order : 63511

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                NFPA 1192 CODES )

```

```

*****
Job # Part No Description          PARTS          Bill to  Qty    Price    Total
*****
PDINT 13034   55362 STD BATTERY              I-PDI      1      10.95    10.95
FPDIN DC-24   ADVANCE GROUP 24 D              I-PDI      1     126.99   126.99
FPDIN 24181   -50 RV ANTI-FREEZE GALLON        I-PDI      0       4.99     0.00
1      10-2067 PLEATED SHOWER DOO      I-DO       1     117.99   117.99
1      500627  SILICONE - N PLUS - CLEAR        I-DO       1      10.99    10.99
3      219088  SILICONE II BLACK                 W-49672    1       9.76     9.76

```

```

*****
Job#  Lab Code Description          LABOUR    Mech Bill to    Hrs    Rate    Total
*****
DINTT Z991    MISC LABOUR CODE (INTE JP    I-PDI      0.63   130.00    81.90
DINTT Z991    MISC LABOUR CODE (INTE JP    I-PDI      0.08   130.00    10.40
DINTT Z991    MISC LABOUR CODE (INTE JP    I-PDI      1.14   130.00   148.20
DINTT Z991    MISC LABOUR CODE (INTE JP    I-PDI      0.39   130.00    50.70
DINTT Z991    MISC LABOUR CODE (INTE JP    I-PDI      3.29   130.00   427.70
DINTT Z991    MISC LABOUR CODE (INTE JP    I-PDI      0.47   130.00    61.10
DINTT PDINTT  PDI - NEW TRAVEL TRAIL JP    I-PDI      2.00   130.00   260.00
      1 Z990    MISC LABOUR CODE (EXTE JP    I-DO       2.00   130.00   260.00
      SWAP Z990  MISC LABOUR CODE (EXTE JP    I-DO       1.30    85.00   110.50
      WALK Z990  MISC LABOUR CODE (EXTE EF    I-PDI      1.50   130.00   195.00
      2 Z990    MISC LABOUR CODE (EXTE JP    W-49672    0.25   130.00    32.50
      2 Z990    MISC LABOUR CODE (EXTE JP    W-49672    1.25   130.00   162.50
      2 Z990    MISC LABOUR CODE (EXTE JP    W-49672    0.00   130.00     0.00
      3 Z990    MISC LABOUR CODE (EXTE JP    W-49672    0.50   130.00    65.00

```

```

*****
Job #  Excode  Description          EXTRAS          bill to    Qty    Price    Total
*****
DINTT  SS      SHOP SUPPLIES              I-PDI      1.00    35.00    35.00
DINTT  LPGI    LP - UNIT SALES            I-PDI      0.00     0.00     0.00
      1  FRT    FREIGHT-SHOWER DOOR        I-DO       1.00    12.49    12.49

```

CUSTOMER COMMENTS

SHOWER DOOR IN BACKROOM 3-4-21...CAM

031821-1

BILLINGS SUMMARY

```

Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I      DO          128.98    370.50    0.00     12.49    0.00    511.97
I      PDI          137.94    1235.00    0.00     35.00    0.00    1,407.94
W      49672         9.76     260.00    0.00     0.00    0.00    269.76

```

Continued on page 3

Work Order : 63511

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
Totals           276.68    1865.50      0.00      47.49      0.00    2,189.67
    
```