



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 63578
Promised Date: 12 MAR 21

CUSTOMER WORK ORDER

WO #: 63578

Customer: 50993 - HEISTAND, JAMIE -
765-505-8646

Tag:
Author: BH
Location: 0312 DELIVERY

Stock #: 10726
Stock Desc: 2021 TT KEYSTONE
SPRINGDALE 1760BH
Chassis #: 4YDT17619MW107339
Serial #: 4YDT17619MW107339
Mileage:
Licence:

Invoice #:
Date In: 11 MAR 21
Promised: 12 MAR 21
Date Sched:
Completed: 18 MAR 21
Warr. Date: 11 MAR 21

Job #BUNKHOUSE - Internal

PRE DELIVERY INSPECTION NEW BUNKHOUSE

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	TEL	N/C

Parts Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
LPG	LP GAS	0.00	N/C	N/C
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BUNKHOUSE: 0.00

Job #BUNKFINAL - Internal

FINAL PDI NEW BUNKHOUSE

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	TEL	N/C

Parts Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #BUNKFINAL: 0.00

Job #E2 - Internal

10K E2 EQUALIZER HITCH

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	TEL	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	TEL	N/C

Parts Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Customer #: 50993
HEISTAND, JAMIE



Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00**Job #JACK - Internal**

INSTALL ELECTRIC TONGUE JACK

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	TEL	N/C

Parts

Part #	Description	Qty	Price	Total
3291	3500# STROMBERG EL	1.00	N/C	N/C

Subtotal for Job #JACK: 0.00**Job #WALK - Internal**

COMPLAINT: WALK THRU

CORRECTION: CUSTOMER DID NOT WANT A WALK THRU, HE KNOWS EVERYTHING THERE IS TO KNOW ABOUT THEM ACCORDING TO HIM
HOOKED UP HITCH GAVE CUSTOMER KEYS, TEMP TAG IN THE WINDOW
Estimated Amount: 180.00

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	EF	N/C

Subtotal for Job #WALK: 0.00**Job #1 - Warranty**

COMPLAINT: WATER LEAK AT THE WATER HEATER INLET
LINE WAS LEAKING

CAUSE: water leak at the water
heater inlet

CORRECTION: saw water dripping out the
bottom of the trailer removed lower bunk
to access water heater replaced cone
washer checked for leaks put bunk back
together

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	TEL	65.00

Parts

Part #	Description	Qty	Price	Total
10-7150	CONE WASHER SWIVEL SEAL	1.00	0.24	0.24

Subtotal for Job #1: 65.24**Job #2 - Internal**

ADJUSTABLE REGULATOR SWAP PER CHAD

Parts

Part #	Description	Qty	Price	Total
40052	40052 BRASS W.P. R	-1.00	N/C	N/C



40064

40064 BRASS REG W/

1.00

N/C

N/C

Subtotal for Job #2:**0.00**

Parts Total: 0.24

Labour Total: 65.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 65.24

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 18 Mar 2021



Authorization number PA02777961 Reference no: 63578

Approved date 3/18/2021

4YDT17619MW107339 3/11/2021

Ju Root ce operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6101414B Fresh Water Pres	0.00	0.50	0.20		1	0.20	Complaint:WATER LEAK AT THE WATER HEATER INLET LINE WAS LEAKING Cause:water leak at the water heater inlet Correction:saw water dripping out the bottom of the trailer removed lower bunk to access water heater found that the cone washer was leaking replaced cone washer checked for leaks put bunk back together KRV - Time approved per flat rate.

0.20

For paper claims only use one pre-authorization number per warranty claim for a claim. Please include a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the