



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 63710

CUSTOMER WORK ORDER

WO #: 63710

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: IH

Stock #: 10977

Stock Desc: 2021 5W KEYSTONE

COUGAR 368MBI

Chassis #: 4YDF36822M2509377

Serial #: 4YDF36822M2509377

Mileage:

Licence:

Invoice #:

Date In: 24 MAR 21

Promised:

Date Sched:

Completed: 31 MAR 21

Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CORRECTION: close up unit and bring in, fill LP tanks 12 Gallons LP, install test battery, check lights, brakes, breakaway, tires, lug nuts, install drain pugs, fill water tanks, check roof, water systems, electric systems, refer, furnace, water heater, TV, radio, microwave, drain tanks, drain water heater

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPG	LP GAS	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: SHADE IN THE LITTLE BED ROOM IS PULLED LOOSE (NOD)

CAUSE: screw pulled out of wall

CORRECTION: remove valance, install shade with 3 screws at top, install valance, readjust string tension,

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	65.00

Subtotal for Job #1: 65.00

Parts Total: 0.00
Labour Total: 65.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 65.00

Customer #: 1000
BASDEN'S AMERICAN RV,

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 01 Apr 2021

Customer Work
Order



e-Authorization

3-Authorization number PA02785326	Reference no: 63710	Status: Approved	Approved by rodri	Approved date 3/29/2021
Trucking Name	Address	VIN	Retail sold on	
aler				

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDF36822M2509377	
----	----------------------	---	-------------------	--

du Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3300214A Blind - Venetian -	0.00	0.75	0.50		1	0.20	Complaint: SHADE IN THE LITTLE BED ROOM IS PULLED LOOSE (NOD) Cause: screw pulled out of wall Correction: remove valance, install shade with 3 screws at top, install valance, readjust string tension, KRV time allowed for adequate repair.

3-Authorization number PA02785326

0.50

r paper claims only use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the