



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 63745

CUSTOMER WORK ORDER

WO #: 63745

Customer: 50049 - SIMMONS,
GREGORY L. - 812-459-0172

Tag:

Author: BJW

Location: 0331 GET COMPLETE ASAP

Stock #: 10347

Stock Desc: 2020 TT COACHMEN
FREEDOM EXPRESS 310BHDSLE

Chassis #: 5ZT2FEWB4LW010642

Serial #: 5ZT2FEWB4LW010642

Mileage:

Licence:

Invoice #:

Date In: 29 MAR 21

Promised:

Date Sched:

Completed: 31 MAR 21

Warr. Date: 11 JUN 20

Job #1 - Internal

COMPLAINT: CHECK FOR LEAK BEHIND CITY WATER CONNECTION.
SEE BW FOR DETAILS. ALSO, WHEN WATER WAS LEAKING IT WAS RUNNING BACK IN TO THE RV
AND FLOODED THE FLOOR. CUSTOMER STATED THAT IT FELT LIKE THE FLOORING WAS
DELAMINATING WHILE CUSTOMER WAS ON VACATION. THE FLOOR DID FEEL MORE SOLID WHEN
CUSTOMER WAS SHOWING UNIT TO BW.

CAUSE: CITY WATER INLET IS LEAKING.

CORRECTION: REPLACED CITY WATER INLET ADAPTER AND REPLACED CRIMP RING.
PRESSURIZED SYSTEM TO CHECK FOR LEAKS, SECURED INLET TO OUTSIDE WALL

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES THAT THE DUCT WORK THAT WAS ON THE BACK OF THE
FURNACE CAME LOOSE. SEE BW FOR DETAILS.

CAUSE: duct came loose from furnace

CORRECTION: cut off small section of duct work where it was damaged. removed piece that attached to
furnace and secured duct work to piece. secured to furnace.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	117.00

Subtotal for Job #2: 117.00

Parts Total:	0.00
Labour Total:	117.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	117.00



Customer #: 50049
SIMMONS, GREGORY L.



