



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 63871

CUSTOMER WORK ORDER

WO #: 63871

Customer: 50310 - HAYNES, MARY L. -
618-732-8576

Tag:
Author: BH
Location: IH

Stock #: 10393
Stock Desc: 2020 5W KEYSTONE
MONTANA 3791RD
Chassis #: 4YDF37927L4701272
Serial #: 4YDF37927L4701272
Mileage: 0
Licence:

Invoice #:
Date In: 09 APR 21
Promised:
Date Sched:
Completed: 09 APR 21
Warr. Date: 08 AUG 20

Job #SUMMER - Internal

COMPLAINT: DE-WINTERIZE UNIT

CORRECTION: bring in unit and open up, bedroom slide will not open, found wires loose on controler for LCI swinnteck in basement of unit, install drain pugs reset, bypass valves, flush atifreeze out of system, unit has washer conetions in bedroom colset, ice maker in residencel refer, out side showerl

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Subtotal for Job #SUMMER: 0.00

Job #1 - Warranty

COMPLAINT: FRONT SLIDE WILL NOT GO OUT.

CAUSE: bedroom slide will not open, found wires loose on controler for LCI swinnteck in basement of unit.

CORRECTION: FOUND NO POWER TO RIGHT FRONT MOTOR. WIGGLE PLUG DOWN AT CONTROL AND FOUND IT WOULD WORK THEN QUIT. PUSH CONNECTOR BACK IN PLUG AND REINSTALLED AND TESTED AND FOUND WORKING FINE NOW.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	288.60

Subtotal for Job #1: 288.60

Parts Total:	0.00
Labour Total:	288.60
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	288.60

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer #: 50310
HAYNES, MARY L.



e-Authorization

4/14/20
11:41:00

3-Authorization number PA02795745 Reference no: Status: Approved Approved by perry Approved date 4/12/2021
 Pricing Name Address Address VIN Retail sold on

94 Basden's American RV Basden's American RV 4YDF37927L4701272 10/8/2020
 600 E Baseline Rd
 Evansville, IN 47725

RV Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1211326A Slide Out Mechan	0.00	2.00	1.00		1	0.40	Complaint:FRONT SLIDE WILL NOT GO OUT. Cause:bedroom slide will not open, found wires loose on controller for LCI Schwintek, in basement of unit. Correction:REPAIRED WIRING AND TESTED AND FOUND WORKING FINE NOW
				1.00				

Approval Statements
 KRV – Labor time approved and adjusted in accordance with
 Keystone RV's flat rate manual.

1 paper claims only use one pre-authorization number per warranty claim for
 please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the