



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64089
Promised Date: 07 MAY 21

CUSTOMER WORK ORDER

WO #: 64089

Customer: 51207 - MEUNIER, KEVIN W.
- 812-217-9897

Tag:

Author: BH

Location: DELIVERY0507

Stock #: 10703

Stock Desc: 2021 TT KEYSTONE
SPRINGDALE 260BH

Chassis #: 4YDT26026M3110418

Serial #: 4YDT26026M3110418

Mileage: 0

Licence:

Invoice #:

Date In: 03 MAY 21

Promised: 07 MAY 21

Date Sched:

Completed: 30 MAY 21

Warr. Date: 07 MAY 21

Job #BUNKHOUSE - Internal

COMPLAINT: PRE DELIVERY INSPECTION NEW BUNKHOUSE

CAUSE: pdintt bunkhouse

CORRECTION: pdintt bunkhouse

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	8.00	N/C	N/C
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #BUNKHOUSE: 0.00

Job #BUNKFINAL - Internal

COMPLAINT: FINAL PDI NEW BUNKHOUSE

CAUSE: fpdi

CORRECTION: fpdi

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 D	1.00	N/C	N/C
55-8171	CIRCUIT BREAKER-20A	1.00	N/C	N/C

Subtotal for Job #BUNKFINAL: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT



Customer #: 51207
MEUNIER, KEVIN W.



Parts				
Part #	Description	Qty	Price	Total
40052	40052 BRASS W.P. R	1.00	N/C	N/C
13-3007	NUGEN 200Z.	1.00	N/C	N/C
22594	22594 25' EVOFLEX	2.00	N/C	N/C
13-0181	40274 2-PLY TST TO	1.00	N/C	N/C
5504	A10-1530AVP 15A-30	1.00	N/C	N/C
11-0018	39741 20' RHINOFLE	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: E2

CORRECTION: E2 INSTALL AND SETUP

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		GWG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		GWG	N/C
Parts				
Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION H	1.00	N/C	N/C
Subtotal for Job #E2:				0.00

Job #WALK - Internal

COMPLAINT: WALK THRU

CAUSE: WALK - WALK THRU.

CORRECTION: Moved unit to walk thru area. Set up unit. Performed walk thru with customer. Instructed customer on hooking up trailer and installing sway bars.

Estimated Amount: 180.00

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Subtotal for Job #WALK:			0.00

Job #1 - Warranty

COMPLAINT: STAB JACK DOES NOT WORK

CAUSE: rear staybilizer jack does not work

CORRECTION: removed switch and found when they drilled hole for switch they hit the circuit breaker with hole saw. when mounting switch they ran mounting screw through the breaker. removed breaker switch then installed breaker under trailer

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	GWG	78.00
Subtotal for Job #1:			78.00

Job #2 - Warranty

COMPLAINT: FRIDGE UPPER DOOR HAS DENT

CAUSE: fridgebottom door the corner is scratched up



CORRECTION: sanded and polished plastic corner on door

Labor

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	GWG	65.00

Subtotal for Job #2: 65.00

Parts Total: 0.00

Labour Total: 143.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 143.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Jun 2021

W/O: 64089
Promised Date: 07 MAY 21



Customer #: 51207
MEUNIER, KEVIN W.



e-Authorization

6/9/20
06:39:21

Authorization number PA02841931 Reference no: 64089 Status: Approved Approved by flins Approved date 6/7/2021
Retail sold on

Basden's American RV
Basden's American RV
600 E Baseline Rd
Evansville, IN 47725
4YDT26026M3110418 5/8/2021

Ju Root e operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1202414A Stabilizer Jack	0.00	0.60	0.60		1	0.50	Complaint:STAB JACK DOES NOT WORK Cause:ATTEMPTED TO RUN STAB JACK AND FOUND IT TO BE INOPERATIVE. INSPECTED FURTHER AND removed switch and found when they drilled hole for switch they hit the circuit breaker wiht hole saw . when mounting switch tey ran mounting screw through the breaker. Correction:removed breaker switch then installed breaker under trailer
2	4123308B Refrigerator - Don	0.00	0.50	0.50		1	0.50	Complaint:FRIDGE UPPER DOOR HAS DENT Cause:fridge bottom door the corner is scratched up Correction:sanded and polished plastic corner on door
3-Authorization number PA02841931				1.10				

r paper claims only use one pre-authorization number per warranty claim for
ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the