



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64167

CUSTOMER WORK ORDER

WO #: 64167

Customer: 11835 - SCHAEFER,
DOUGLAS L. - 812-477-6315

Tag:

Author: BH

Location: 0514 CHECK FOR APPROVAL
FROM EIVERSIDE 0515NEEDS BACK

Stock #: 10618

Stock Desc: 2021 TT RIVERSIDE RV
INTREPID 257RKS

Chassis #: 59CCC3525ML002930

Serial #: 59CCC3525ML002930

Mileage: 0

Licence:

Invoice #: 361120

Date In: 10 MAY 21

Promised:

Date Sched:

Completed: 14 MAY 21

Warr. Date: 14 JUL 20

Job #1 - External

COMPLAINT: CHECK ROOF

CORRECTION: Roof looks good

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: CHECK CAMERA GOES ON AND OFF

CORRECTION: AFTER REMOVING CAMERA .FOUND WIRE LOOSE ON PLUG AND PLUG LOOKED BAD. CUT OFF PLUG AND HARD WIRED. WORKS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: WATER HEATER DOES NOT WORK ON ELE

CORRECTION: REMOVED ELEMENT COVER. PLUGGED UNIT IN. DID AAMP DRAW ON CONVETOR. NO DRAW. DID OMNS TEST ON ELEMENT AND FOUND IT IS BAD. TOOK PICS. PUT NEW ELEMENT IN AND THE AMP DRAW WAS 10.67

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	65.00

Subtotal for Job #3: 65.00

Job #4 - Internal

COMPLAINT: INSTALL BUBBLE LEVEL ON REAR OF UNIT THAT IS SITTING ON THE KITCHEN COUNTER

CORRECTION: PUT BUBBLE ON REAR



Customer #: 11835
SCHAEFER, DOUGLAS L.



Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #4: 0.00

Comments

RONNIE @ SUBURBAN SENDING REPLACEMENT ELEMENT. IT GOES INTO STOCK. SALES ORDER/AUTH#679618 PAYS .5 PART MUST BE RETURNED.

Parts Total:	0.00
Labour Total:	65.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	65.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 May 2021

Customer Order

