



# Warranty Authorization Form

Date: 11/26/2024

Basden RV Center, Inc. DBA/ American RV  
600 E Baseline Rd  
Evansville, IN 47725  
Ph. (812) 867-5200  
cbruce@americanrvcenter.com

### General Information

Pre-Auth #: 79757 Unit: 7M5FP4323RB203763  
Series: Paradigm Model: 2024PAR395DS  
Notes:  
Status: Approved with Modifications

### Dealer Information

American RV  
(812) 867-5200  
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV  
600 E Baseline Rd  
Evansville, IN 47725

Requestor: Ben Hoffman  
Return Fax #:  
Email: bhoffman@americanrvcenter.com

### Operation Line 1

Flat Rate Code: 14050 DOOR - INTERIOR - SLIDING - ADJUST

Fault Code: IMPROPERLY INSTALLED

Serial #:

Model #:

Notes:

Problem: CHECK SLIDING BATHROOM DOORS, FRONT ONE IS OPENING WHILE GOING DOWN THE ROAD AND THE TRACK IS LOOSE IS ON THE REAR ONE

Time Requested: .2

Cause: check rear slide door to bathroom and front bathroom

Time Allowed: .2

Remedy: rear bathroom door was off of track,put door back on track,front bathroom slide door,moved strap back to put more tension on door.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

### Operation Line 2

Flat Rate Code: 12022 COMPARTMENT DOOR - SEAL - REPLACE (Photo required)(Vendor auth required)

Fault Code: IMPROPERLY INSTALLED

Serial #:

Model #:

Notes:

Problem: CUSTOMER STATED THAT THE FRONT STORAGE COMPARTMENT ON THE DOOR SIDE LEAK A LITTLE WATER ON LAST TRIP

Time Requested: .4

Cause: front storage compartment on door side has gotten water in it.

Time Allowed: .2

Remedy: took pictures and found seal has several tear spots in it,took off old seal and installed new seal.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved with Modifications

**Operation Line 3**

*Flat Rate Code:* 22586 SEWER CAP - REPLACE

*Fault Code:* BROKEN

*Serial #:*

*Model #:*

*Notes:*

*Problem:* REAR SEWER CAP BROKE

*Time Requested:* .1

*Cause:* rear sewer cap broken

*Time Allowed:* .1

*Remedy:* took pictures and installed new cap.

*Sublet Repairs:* 0.00

*Part Return Req:* No

*Status:* Approved