



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 79394  
Promised Date:  
21 MAR 26

### CUSTOMER WORK ORDER

WO #: 79394 (Appointment Date: 28 MAR 2026 - Time: 09:30am)  
 Customer: 53191 - SCHROEDER, PATRICK - 812-449-3775  
 Tag:  
 Author: BJW  
 Location: 0406 BH TO CLOSE

Stock #: 11492  
 Stock Desc: 2025 TT COACHMEN APEX NANO 208BHS  
 Chassis #: 5ZT2CXKB6SL017912  
 Serial #: 5ZT2CXKB6SL017912  
 Mileage: 0  
 Licence:

Invoice #:  
 Date In: 28 MAR 26  
 Promised: 31 MAR 26  
 Date Sched:  
 Completed: 06 APR 26  
 Warr. Date: 29 APR 25

#### Job #1 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE WATER PUMP ONLY RUNS INTERMITTANTLY

CAUSE: Water pump intermittent runs

CORRECTION: On inspection of the water pump i have good pressure at my faucet but the water pump never shuts off and it was real hot to the touch. I tried pulling from water tank and turn it on winterize mode and pull from a bucket same results. So i put in for a new water pump. And it works properly and now leaks.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	97.50

#### Parts

Part #	Description	Qty	Price	Total
333426	Pump - Water - Revolution - 12V - 3	1.00	57.28	57.28
10-7150	CONE WASHER SWIVEL SEAL	2.00	0.26	0.52

**Subtotal for Job #1: 155.30**

#### Job #2 - Internal

COMPLAINT: THE BATTERY DOES NOT LAST VERY LONG WHEN RUNNING THE REFRIGERATOR ON BATTERY ONLY. IT WON'T LAST A FULL DAY.

CAUSE: Battery doesn't last all day running refrigerator only

CORRECTION: So after my inspection of the system. I load tested both batteries and they were good. Batteries had 12.78 volts. Plugged into shore power they were at 13.78 volts. Solar panel said 14.0. Took unit off shore power and turned the regulator on and batteries checked 13.3. Going to sit it outside and test how system works last checked at 4pm on Friday the batteries were 12.96 and refrigerator was cold. It probably was the bad water pump that kept running. That i replaced the water pump

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C



Customer #: 53191  
SCHROEDER, PATRICK

Subtotal for Job #2: 0.00

**Job #3 - Warranty**

COMPLAINT: CUSTOMER ADVISES THAT THE A/C RATTLES WHEN RUNNING ON HIGH FAN SETTING.

CAUSE: Ac making a rattle sound when on high

CORRECTION: So inspection of the ac unit and i heard the rattle or vibration sound. So i took the inside trim ring down and turn the ac back on and the sound went away. So i noticed there was a wire with a plastic connector on it laying loose. ( it was used for a different style controls) so i zip tie it to a group of wires and put it back together and turn it on each setting and no rattle. Ac good to go

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	97.50

**Subtotal for Job #3: 97.50**

Parts Total: 57.80  
 Labour Total: 195.00  
 Sublet Total: 0.00  
 Extras Total: 0.00

**WORK ORDER TOTAL: 252.80**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature \_\_\_\_\_

Date: 06 Apr 2026

W/O: 79394  
Promised Date: 31 MAR 26



Customer #: 53191  
SCHROEDER, PATRICK

