



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79552
Promised Date:
26 APR 26

CUSTOMER WORK ORDER

WO #: 79552 (Appointment Date: 13 APR 2026 - Time: 07:00am)

Customer: 55914 - ADAMS, JOSHUA -
573-352-1073

Tag:

Author: BJW

Location: 0414 BH TO CLOSE

Stock #: 11602

Stock Desc: (11602) 2025 COACHMEN

CATALINA SUMMIT 281QBUNK

Chassis #: 5ZT2CATB5SN301421

Serial #: 5ZT2CATB5SN301421

Mileage:

Licence:

Invoice #:

Date In: 13 APR 26

Promised: 30 APR 26

Date Sched:

Completed: 14 APR 26

Warr. Date: 18 JUL 25

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THEY HAVE A WATER LEAK ON REAR NON DOOR SIDE BY CITY AND FRESH WATER FILL. WE REPLACED WATER PUMP AND WINTERIZEE IN NOVEMBER. CUSTOMER STATES THERE WAS NO LEAK BEFORE. CUSTOMER SAYS THE BLUE HOSE COMING THROUGH THE FLOOR TO THE PUMP IS CROSS THREADED AND LEAKING. CUSTOMER ADVISES THAT WHEN THE PUMP DOES PUMP, IT DOES NOT HAVE MUCH PRESSURE.

CAUSE: Water pump has no pressure and city water inlet leaking

CORRECTION: On inspection of the system. I found the city water inlet check valve was missing the cone washer so i put a new one in it and no more leaks. I put budle tape behind it and sealed with clear silicone. The water pump the outlet side was cross threaded and was leaking. So i fixed that. Once I got those to things fixed the water pump had pressure and works properly with no leaks. So i cleaned up my mess and put the drawers and converter back in had to take out to get to the water pump. Outlet side was cross threaded and leaking and city water inlet was leaking. So once i got them fixed system works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	146.25

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 146.25

Job #2 - External

UNIT WILL BE IN PARKING LOT MONDAY MORNING.

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: CUSTOMER STATES WATER PUMP HAS LOW PRESSURE

CAUSE: Water pump has no pressure

CORRECTION: Outlet side was cross threaded and leaking and city water inlet was leaking. So once i got them fixed system works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C



Customer #: 55914
ADAMS, JOSHUA

Subtotal for Job #3: 0.00

Parts Total: 0.00
Labour Total: 146.25
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 146.25

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 Apr 2026

Customer Work Order

W/O: 79552
Promised Date: 30 APR 26



Customer #: 55914
ADAMS, JOSHUA

