



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77347
Promised Date:
24 JUL 25

CUSTOMER WORK ORDER

WO #: 77347 (Appointment Date: 22 JUL 2025 - Time: 09:00am)

Customer: 54431 - COOK, JAMES -

Tag:

Author: GA

Location: 0815 CHECK WORK

Stock #:

Stock Desc: 2023 TT KEYSTONE

BULLET BL287QBS23

Chassis #:

Serial #: 4YDTBLN29PT431168

Mileage:

Licence:

Invoice #:

Date In: 22 JUL 25

Promised: 31 JUL 25

Date Sched:

Completed: 15 AUG 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: WE HAVE REPLACED THE AIR CONDITIONER ON THIS UNIT IN THE PAST. WHEN CUSTOMER ATTEMPTS TO RUN THE FRONT UNIT FAN ON AUTO, NOTHING RUNS AT ALL. WHEN HE RUNS THE FAN ON HIGH OR LOW, IT WILL RUN, BUT THE COMPRESSOR KICKS OUT RIGHT AWAY AND IT DOES NOT COOL.

CAUSE: Air conditioner not working

CORRECTION: I found that the air conditioner is not pulling enough amperage. This is a sign of low coolant. The air conditioner will need to be replaced.

I removed the old air conditioner and installed the new air conditioner. I had to tape up the air box after i reinstalled the plenum. I tested the air conditioner after the installation was completed. After 20 minutes of run time, the intake is 77 and the discharge is 53. It is now working as it should.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	333.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	37.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
PARTS	30% HANDLEING FEE	1.00	172.42	172.42

Subtotal for Job #1: 542.42

Parts Total:	0.00
Labour Total:	370.00
Sublet Total:	0.00
Extras Total:	172.42
WORK ORDER TOTAL:	542.42

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer #: 54431
COOK, JAMES

