

GREENEWAY, INC.  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS WI  
 US  
 54494  
 (715) 325-5170

WORK ORDER # 12058

Date In: 16 MAY 25	Author: DLUCAS
Promised Date: 14 JUL 25	Stock No: 11117
:	Year: 2024
Customer Name: 108936 - DIETSCH, STE	Manufacturer: CROSSROADS
Address: N8669 ROMADKA AVE	Brand: HAMPTON
: LOYAL, WI	Model: 390PVL
Postal/Zip: 54446	Miles/Hrs: 0
Phone#(res): 715-650-7852	Exterior Color:
Phone#(bus):	Unit Type: TT-TRAVEL TRAILER
Cell Phone:	License#:
Email: NONE	Tag#: 6/6
Purchased Date: 16 MAY 25	:
Delivery Date: 20 MAY 25	:
InService Date:	:
Serial#: 4YDTHPU23R9330277	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
1       COMPLAINT: TOW: GMC 2500 BC: Y TP: Y HITCH: ON BALL I   DO   DEALE
        - WAIVER
        CORRECTION: NOTING
PDIT    COMPLAINT: SOLD FINISH PREP TRAVEL TRAILER                I   PDI   PRE-D
        CAUSE: SOLD FINISH PREP
        CORRECTION: COMPLETE
CEN     COMPLAINT: CLEAN EXTERIOR- NEW                                I   PDI   PRE-D
        CAUSE: DIRTY
        CORRECTION: CLEAN
CIN     COMPLAINT: CLEAN INTERIOR- NEW                                I   PDI   PRE-D
        CAUSE: DIRTY
        CORRECTION: CLEAN
ST      COMPLAINT: SHOWTHRU&SHOWOUT SALESMAN: DAKOTA                I   PDI   PRE-D
        CAUSE: Showthru
        CORRECTION: Showed customers there brand new camper
        and hooked them up and sent them down
        the road
WARR    COMPLAINT: WARRANTY REPAIR 10 - missing dust cap ds W      1047  CROSS
        rear axle.
        CAUSE: Missing dust cap on ds rear axle.
        CORRECTION: Installed new cap.
2       COMPLAINT: ON THE DAY OF THE SHOWTHRU- THE TECH WAS I   SEP   POLIC
        BRINGING THE UNIT INTO THE SHOP AND THE
        AC DAMAGED- NEEDS TO BE REPLACED-
        CAUSE: replace damage rear ac above loft
        CORRECTION: remove and installed the new rear ac and
        tested ok
3       SERVICE CALL TO CUSTOMERS SITE AT: HATFIELD RUSSEL I   SEP   POLIC
*****
```

Continued on page 2

Work Order : 12058

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
MEMORIAL PARK SITE: 187
4      COMPLAINT:  WHEN AT THE SITE FOR THE AC REPAIR- NEED W   1047   CROSS
        TO ISNTALL THE TENSION CABLES FOR THE
        MIDDLE BLIND AND THE BEDROOM BLIND THAT
        OPERATE VIA MOTOR
        CAUSE:      pics taken will need a new shade and
        sting for tension
        CORRECTION: Will need a new shade with tension sting
        ... REQUEST .50 HOURS OF LABOR
5      COMPLAINT:  ON THE DAY OF THE SHOWTHRU FOUND THAT   W   1047   CROSS
        THE REGISTER BEHIND THE COUCH IS CRACKED
        AND NEEDS TO BE REPLACED-
        CAUSE:      melted floor vent in living room
        CORRECTION: remove and install floor vent now ok
        REQUEST .20 HOURS OF LABOR
6      COMPLAINT:  LEFT SIDE OF COUCH FALLS BACK CUSTOMER   W   1047   CROSS
        WOULD LIKE LOOKED AT.
        CAUSE:      needed screws to secure the back of
        couch
        CORRECTION: install 4 screws in wooden pegs to
        secure back of couch now ok   REQUEST
        .20 HOURSOF LABOR
7      COMPLAINT:  NEED MEASUREMENTS OF SCREEN DOOR AS IT   W   1047   CROSS
        WAS MISSING
        CAUSE:      SCREEN DOOR 30*72
        CORRECTION: NEED TO ORDER SCREEN DOOR   REQUEST .20
        HOURS OF LABOR
8      COMPLAINT:  CUSTOMER STATES WATER HEATER IS SPRAYING W   1047   CROSS
        COLD WATER OUT OF SHOWERHEAD IN BATHROOM
        AT RANDOM, IS NOT GETTING ANY HOT WATER
        OUT OF KITCHEN SINK
        CAUSE:      checked for hot water in kitchen sink
        and bathroom shower
        CORRECTION: checked hot water at kitchen sink you
        need to pull handle toward you and the
        shower is perfectly normal operation as
        well   REQUEST .30 HOURS OF LABOR
    
```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty   Price   Total
*****
WARR1 822059420      Axle - Dust Cap - w/RBR W-1047   1       7.27    7.27
CIN   019079236326  TOILET TISSUE, SGL. 2 PL I-PDI   1       1.02    1.02
CIN   014717396042  HTS STANDARD 10' SEWER H I-PDI   1       7.46    7.46
CIN   019079900142  PARK ADAPTER BULK 30-15 I-PDI   1       2.33    2.33
2     CMN37207-079  MACH 8 POWERSAVER A/C BL I-SEP   0     1,269.01  0.00
5     82204495      GRILL- REGISTER 4X10 BRO W-1047   0       8.15    0.00
PDITT 840821034507  12V 24 MDP BATTERY           I-PDI   1       85.20   85.20
2     822027775      A/C - 11.0 BTU - Mach 8 I-SEP   0       0.00    0.00
    
```

Continued on page 3

Work Order : 12058

```
*****
Job # Part No      Description      PARTS    Bill to    Qty    Price    Total
*****
3      82204495      GRILL- REGISTER 4X10 BRO I-SEP      1      8.15      8.15
3      822027775      A/C - 11.0 BTU - Mach 8 I-SEP      1      0.00      0.00
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
PDITT RV1F-3B SOLD FINISH PREP TRAVE CF I-PDI 0.50 70.00 35.00
CEN CE CLEAN EXTERIOR EJ I-PDI 0.98 70.00 68.60
CIN CI CLEAN INTERIOR SL I-PDI 3.61 70.00 252.70
ST RV1D-3 SHOW THRU & PICK UP PD CF I-PDI 2.00 70.00 140.00
ARR10 Z992 MISC LABOUR CODE (WARR TD W-1047 0.50 140.00 70.00
2 RV31I-1 AIR CONDITIONER R&R IN JS I-SEP 2.00 70.00 140.00
ST RV1D-3 SHOW THRU & PICK UP PD CF I-PDI 2.00 70.00 140.00
4 WARR MANUFACTURER WARRANTY JS W-1047 0.50 140.00 70.00
5 WARR MANUFACTURER WARRANTY JS W-1047 0.50 140.00 70.00
6 WARR MANUFACTURER WARRANTY JS W-1047 0.25 140.00 35.00
8 WARR MANUFACTURER WARRANTY JS W-1047 0.50 140.00 70.00
7 WARR MANUFACTURER WARRANTY W-1047 0.00 140.00 0.00
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
PDITT LP PROPANE I-PDI 60.00 0.74 44.40
ARR10 SSE SHOP SUPPLIES - EXTERNAL W-1047 1.00 0.00 0.00
3 SC SERVICE CALL I-SEP 58.00 3.75 217.50
5 FRT FREIGHT FOR JOB 5 REGISTER W-1047 1.00 20.64 20.64
2 FRT FREIGHT FOR JOB 2 I-SEP 1.00 177.49 177.49
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
I PDI 96.01 636.30 0.00 44.40 0.00 776.71
I SEP 8.15 140.00 0.00 394.99 0.00 543.14
W 1047 7.27 315.00 0.00 20.64 0.00 342.91

Totals 111.43 1091.30 0.00 460.03 0.00 1,662.76
*****
```

&k2S  
&k0S