

GREENEWAY, INC.  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS WI  
 US  
 54494  
 (715) 325-5170

WORK ORDER # 10014B

Date In: 14 DEC 23	Author: MGRAY
Promised Date: 04 JUL 24	Stock No: 11031
:	Year: 2024
Customer Name: 1000 - GREENEWAY RV SA	Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT	Brand: REFLECTION FW
: WISCONSIN RAPIDS, WI	Model: 324MBS
Postal/Zip: 54494	Miles/Hrs: 0
Phone#(res): 800-758-2272	Exterior Color:
Phone#(bus):	Unit Type: FW-FIFTH WHEEL
Cell Phone:	License#:
Email: NONE	Tag#:
Purchased Date:	:
Delivery Date:	:
InService Date:	:
Serial#: 573FR3820R9925547	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 2 -The cabinet door          W    1020    GRAND
        beneath the kitchen sink the top looks
        loose
        CAUSE:      Little chunk of wood was missing causing
        it to look loose at joint
        CORRECTION: I filled with putty
WARR    COMPLAINT:  WARRANTY REPAIR 4 - Mini nicks in the          W    1020    GRAND
        wood throughout the unit
        CAUSE:      Knicks in wood
        CORRECTION: Covered with putty throughout unit took
        3 minutes
WARR    COMPLAINT:  WARRANTY REPAIR 6 - Ds window next to          W    1020    GRAND
        bed has a small chip in it near the top
        CAUSE:      Small chip in window next to bed door
        side chip is near the top left side
        CORRECTION: Please order a 32"x 36" window black
        framed slider window  pics taken of
        name on window and of the chip in window
WARR    COMPLAINT:  WARRANTY REPAIR 7 - the ODS FRONT              W    1020    GRAND
        PASSTHRU compartment under the lino the
        wood underlayment looks like it may have
        gotten wet at one time
        CAUSE:      Mfg defect VERY BUMPY FROM WATER
        INTRUSION
        CORRECTION: I removed saddle box and trim I then
        pulled up lino and sanded down SMAOOTH
        ALSO made sure that nothing was leaking
        on back of water panel or back of water
*****
```

Continued on page 2

Work Order : 10014B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                               heater nothing found I then glued down
                               floor and reinstalled trim saddle box
                               etc
*****

```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
WARR0 822080666 WINDOW 8800 DW 42 X 36 G20  W-1020      1   166.23  166.23
*****

```

```

*****
Job#  Lab Code  Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50  115.00  57.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.00  115.00   0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50  115.00  57.50
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.00  115.00   0.00
ARR06 Z992      MISC LABOUR CODE (WARR RW  W-1020      0.00  115.00   0.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.03  115.00   3.45
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.06  115.00   6.90
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.08  115.00   9.20
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.00  115.00   0.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.02  115.00   2.30
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.48  115.00  55.20
ARR06 Z992      MISC LABOUR CODE (WARR RW  W-1020      0.33  115.00  37.95
ARR06 Z992      MISC LABOUR CODE (WARR RW  W-1020      0.00  115.00   0.00
*****

```

```

*****
Job #  Excode   Description           EXTRAS           bill to   Qty   Price   Total
*****
ARR06  FRT       FREIGHT                       W-1020      1.00   91.80  91.80
*****

```

CUSTOMER COMMENTS

FREIGHT- 91.80- KW

BILLINGS SUMMARY

```

*****
Type Bill Id   Parts   Labour   Sublet   Extras   Tax   Total
*****
W   1020       166.23  230.00   0.00    91.80   0.00  488.03
*****
Totals        166.23  230.00   0.00    91.80   0.00  488.03
*****

```

&k2S  
&k0S