

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 1837472
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2PUPB7P4017561
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 425 / 425
 ITEM # PUT25RKQB-1
 DEALER RO # 10075B
 CLAIM START DATE 03/04/2024
 CLAIM END DATE 08/09/2024

Labor rate: \$115.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-102-01-00-003051 HDF or MDF Paneling - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : afreeman@greenewayrv.com, 2024-03-04 12:00:51 :: Bedroom wall panel HAS GOUGE IN IT, MFG UNSURE CAME IN DAMAGED NEEDS NEW WALL PANEL ORDERED TO BE REPLACED

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$57.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$11.50

Notes
 not noted inDAF

Flat rate add seam tape

Part

Line# 2 **Item #** **Description**
 F100150686 PANELING, 1/8 X 48 X 96 MELIA PLATINUM (WALL BOARD)

Model #	Serial #	Part tag	
Sub Qty	1.00	Sub Dlr Price	\$45.14
Appr Qty	1.00	Sub Freight	\$281.70
		Appr Dlr Price	\$45.14
		Appr Freight	\$281.70

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 20-62-01-00-000650 Interior Vent Garnish - Exterior/Power Roof Vent (Elixir & Hengs)/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : afreeman@greenewayrv.com, 2024-03-04 12:05:02 :: bathroom fan shroud is cracked ,over tourqed screws, REPLACED FAN SHROUD

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$11.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$11.50

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 20-43-24-00-000589 Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : afreeman@greenewayrv.com, 2024-03-04 12:12:06 :: ALL Front decal on front cap is damaged, from sitting for so long outside NEED ALL NEW FRONT DECALS

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$115.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$57.50

Notes

attach photo of all damaged decals
flat rate per photo provided

Part

Line# 1	Item #		Description		
	F100224267		DECAL, PUMA, FRONT DIE CUT #71-LH, 2021, FR-20-75776A-LH		
	Model #		Serial #		Part tag
	Sub Qty	1.00	Sub Dlr Price	\$6.16	Sub Freight
	Appr Qty	1.00	Appr Dlr Price	\$6.16	Appr Freight
					\$13.04
					\$13.04

Notes

Line# 2	Item #		Description		
	F100224265		DECAL, PUMA, FRONT DIE CUT #69-LH, 2021, FR-20-75775A-LH		
	Model #		Serial #		Part tag
	Sub Qty	1.00	Sub Dlr Price	\$9.23	Sub Freight
	Appr Qty	1.00	Appr Dlr Price	\$9.23	Appr Freight
					\$13.05
					\$13.05

Notes

Line# 3	Item #		Description		
	F100225024		DECAL, PUMA, FRONT DIE CUT #51-LH, FR-20-75653A-LH		
	Model #		Serial #		Part tag
	Sub Qty	1.00	Sub Dlr Price	\$7.63	Sub Freight
	Appr Qty	1.00	Appr Dlr Price	\$7.63	Appr Freight
					\$13.05
					\$13.05

Notes

Line# 4	Item #		Description		
	F100224837		DECAL, PUMA, PALOMINO LEGEND, FR-19-70911C		
	Model #		Serial #		Part tag
	Sub Qty	1.00	Sub Dlr Price	\$14.35	Sub Freight
	Appr Qty	1.00	Appr Dlr Price	\$14.35	Appr Freight
					\$4.55
					\$4.55

Notes

Line# 5	Item #		Description		
	F100224836		DECAL, PUMA, LG PUMA LEGEND, FR-20-75651A		
	Model #		Serial #		Part tag
	Sub Qty	1.00	Sub Dlr Price	\$53.36	Sub Freight
	Appr Qty	1.00	Appr Dlr Price	\$53.37	Appr Freight
					\$4.55
					\$4.55

Notes

Line# 6	Item #		Description		
	F100225036		DECAL, PUMA, FRONT DIE CUT #78, FR-20-75788C		
	Model #		Serial #		Part tag
	Sub Qty	1.00	Sub Dlr Price	\$37.12	Sub Freight
	Appr Qty	1.00	Appr Dlr Price	\$37.12	Appr Freight
					\$4.56
					\$4.56

Notes

Line# 7	Item #		Description		
	F100225039		DECAL, PUMA, FRONT DIE CUT #86, FR-20-75879B		
	Model #		Serial #		Part tag
	Sub Qty	1.00	Sub Dlr Price	\$9.07	Sub Freight
	Appr Qty	1.00	Appr Dlr Price	\$9.07	Appr Freight
					\$4.56
					\$4.56

Notes

Line# 8	Item # F100224268		Description DECAL, PUMA, FRONT DIE CUT #71-RH, 2021, FR-20-75776A-RH			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$6.16	Sub Freight	\$4.56
	Appr Qty	1.00	Appr Dlr Price	\$6.16	Appr Freight	\$4.56

Notes

Line# 9	Item # F100224266		Description DECAL, PUMA, FRONT DIE CUT #69-RH, 2021, FR-20-75775A-RH			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$14.91	Sub Freight	\$4.56
	Appr Qty	1.00	Appr Dlr Price	\$14.91	Appr Freight	\$4.56

Notes

Line# 10	Item # F100225030		Description DECAL, PUMA, FRONT DIE CUT #51-RH, FR-20-75653A-RH			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$13.39	Sub Freight	\$4.56
	Appr Qty	1.00	Appr Dlr Price	\$13.39	Appr Freight	\$4.56

Notes

Submitted	Labor Amt	\$184.00	Approved	Labor Amt	\$80.50
	Parts & Freight	\$569.27		Parts & Freight	\$569.27
	Total	\$753.27		Total	\$649.77

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.