

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 10095C

Date In: 19 FEB 25	Author: MZYWICKI
Promised Date: 31 MAY 25	Stock No: 11101
:	Year: 2024
Customer Name: 1000 - GREENEWAY RV SA	Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT	Brand: PUMA DESTINATION
: WISCONSIN RAPIDS, WI	Model: 37PFL
Postal/Zip: 54494	Miles/Hrs: 0
Phone#(res): 800-758-2272	Exterior Color:
Phone#(bus):	Unit Type: TT-TRAVEL TRAILER
Cell Phone:	License#:
Email: NONE	Tag#:
Purchased Date:	:
Delivery Date:	:
InService Date:	:
Serial#: 4X4TPUN26RP101391	:

```

*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
WARR  COMPLAINT:  WARRANTY REPAIR 2 - SEAM TAPE ABOVE          W    1021  FORES
      CAUSE:      SHOWER HAS SMALL BREAK IN IT
      CAUSE:      NOT A BREAK BUT A CREASE IN THE SEAM.
      CAUSE:      NEED TO CUT AND OVER LAY NEW TAPE
      CORRECTION: REQUESTING .40 HOURS
WARR  COMPLAINT:  WARRANTY REPAIR 3 - NOTING THERE IS A        W    1021  FORES
      CAUSE:      SCRATCH ON THE FREEZER DOOR
      CAUSE:      MFG
WARR  COMPLAINT:  WARRANTY REPAIR 4 - TWO OF THE BATON          W    1021  FORES
      CAUSE:      STRIPS BEHIND THE COUCH ARE NOT ATTACHED
      CAUSE:      TO WALL PROPERLY
      CAUSE:      LOOKS LIKE STAPLES DIDNT HOLD BATON
      CAUSE:      STRIPS IN PLACE. WILL NEED TO NAIL DOWN
      CORRECTION: REQUESTING .50 HOURS
WARR  COMPLAINT:  WARRANTY REPAIR 5 - THE SCREEN ON THE        W    1021  FORES
      CAUSE:      WINDOW BY THE DINING ROOM TABLE HAS A
      CAUSE:      BAD SEAL
      CAUSE:      SEAL IS STARTING TO PULL AWAY FROM FRAME
      CAUSE:      AND CAUSE THE MESH TO PULL AWAY FROM
      CAUSE:      FRAME AS WELL CREATING A HOLE. NEED TO
      CAUSE:      REPLACE SCREEN
      CORRECTION: REQUESTING .50 HOURS
*****
  
```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR02 Z992    MISC LABOUR CODE (WARR  W-1021  0.00  115.00  0.00
ARR03 Z992    MISC LABOUR CODE (WARR  W-1021  0.00  115.00  0.00
*****
  
```

Continued on page 2

Work Order : 10095C

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR04 Z992      MISC LABOUR CODE (WARR      W-1021    0.00   115.00    0.00
ARR05 Z992      MISC LABOUR CODE (WARR      W-1021    0.00   115.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
Totals           0.00     0.00     0.00     0.00     0.00     0.00
*****
```

&k2S
&k0S