

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10111

Date In: 02 FEB 24 Author: TPASSER
Promised Date: 12 APR 24 Stock No:
: Year: 2022
Customer Name: 15372 - KUDELA, BRIAN Manufacturer: GRAND DESIGN
Address: 340 COUNTY ROAD O Brand: IMAGINE
: HANCOCK, WI Model: 2910BH
Postal/Zip: 54943 Miles/Hrs:
Phone#(res): 608-387-3883 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: bkakudela@gmail.com Tag#: 4/26 CMR UPDATED - WP
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573TE3423N6641667 :

Job # Description JOB INFORMATION Type Bill To

SC SERVICE CALL TO HANCOCK - 340 COUNTY RD O I SEP POLIC
1 COMPLAINT: INSIDE REAR BUNKHOUSE DOOR POCKET-SCREWS I SEP POLIC
CAME OUT OF TOP TRACK. REPAIRED IH - CMR
PICKED UP UNIT 1/29 AND NOTICED THE
TRACK FELL AGAIN AND NEEDS TO BE REHUNG.
CAUSE: pics taken What I found was the rear
sliding door for bunk room the screw had
pulled from door
CORRECTION: remove upper header disconnected upper
sliding door bracket remove door and
added better screws re attached the door
and tested ok
2 COMPLAINT: 3/5 CUST STATES REAR ENTRY DOOR LOCK IS E 15372 KUDEL
NOT WORKING PROPERLY. ISSUE WITH KEY
GOING INTO CYLINDER AND THEN WILL NOT
LOCK TOP LOCK. PICS WILL BE EMAILED FOR
REPLACEMENT
CAUSE: pics taken rear entry door need a new
lock due to key cylinder falling out and
damaged
CORRECTION: remove the damage rear entry door lock
installed the door lock assembly and
tested both keys the door also latches
and locks as well
3 COMPLAINT: CUSTOMER STATES AWNING IS SEPERATING W 1020 GRAND
FROM UNIT. RECALL LIPPERT 22E-055
CAUSE: LIPPERT RECALL22E-055 AWNING SEPERATION.
CORRECTION: WILL NEED NEW FABRIC FOR REPLACEMENT.

Continued on page 2

Work Order : 10111

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
4       SCA 4/12 WHILE COMPLETING JOB 3 - JS NOTICED AWNING E   15372  KUDEL
       FABRIC SEPERATING AT THE SEAM AND LED LIGHTS NEED TO
       BE REPLACED
*****
```

```
*****
Job # Part No      Description          PARTS    Bill to  Qty    Price    Total
*****
2       711217016691 RV BAUER DOOR LOCK BLACK E-15372    1     56.24    56.24
4       82200728        AWNING 21' BLACK SOLID F E-15372    0     374.97    0.00
*****
```

```
*****
Job# Lab Code Description          LABOUR    Mech Bill to    Hrs    Rate    Total
*****
SC SC          SERVICE CHARGE                I-SEP    0.00    70.00    0.00
1 RV31A-21     DOOR CEILING TRACK R&R JS    I-SEP    0.10    70.00    7.00
2 RV30C-6     ENTRY DOOR ADJUST          JS    E-15372    0.30    115.00    34.50
4 AWN LITE    AWNING LIGHT R & R IN    JS    E-15372    0.50    115.00    57.50
4 RV3-1a     AWNING FABRIC REPLACE      E-15372    0.00    115.00    0.00
3 Z992       MISC LABOUR CODE (WARR    W-1020    0.00    115.00    0.00
*****
```

```
*****
Job # Excode   Description          EXTRAS    bill to  Qty    Price    Total
*****
SC SC          SERVICE CALL                I-SEP    1.00    3.75    3.75
SC SSE        SHOP SUPPLIES - EXTERNAL    I-SEP    1.00    6.90    6.90
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
E   15372          56.24    92.00    0.00    0.00    8.19    156.43
I   SEP           0.00    7.00    0.00    10.65    0.00    17.65

Totals          56.24    99.00    0.00    10.65    8.19    174.08
*****
```

&k2S
&k0S