

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10172B

Date In:	18 MAR 24	Author:	MGRAY
Promised Date:	31 AUG 24	Stock No:	11097
:	:	Year:	2023
Customer Name:	17249 - POWERS, SHERI	Manufacturer:	FOREST RIVER
Address:	N8788 CRASS ROAD	Brand:	PUMA ULTRA LITE
:	TOMAHAWK, WI	Model:	16DSX
Postal/Zip:	54487	Miles/Hrs:	0
Phone#(res):	7156126919	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	sheri.powers@aol.com	Tag#:	:
Purchased Date:	06 MAR 24	:	:
Delivery Date:	16 MAR 24	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUEC9P4018027	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Front cap decal          W    1021    FORES
        TALKED WITH CUSTOMER MIGHT WANT TO JUST
        PICK THEM UP AND NOT HAVE INSTALLED WILL
        DECIED WHEN THEY COME IN. SD 3/16
        CAUSE:        Front cap decal peeling edges For
        warranty, Order front cap decal (Ultra
        Lite) under window
        CORRECTION:    ...
WARR    COMPLAINT:  WARRANTY REPAIR 2 - Refer Shroud bent      W    1021    FORES
        out
        CAUSE:        Combination of the metal siding not cut
        straight and the housing bent at tabs.
        CORRECTION:    Had to remove schroud, trim metal siding
        dipping down in one area, replace
        schroud add two new screws and re-caulk
        housing.
1        COMPLAINT:  CUSTOMER STATES THAT THE COMPARTMENT      W    1021    FORES
        DOOR DOES NOT SIT FLUSH WITH THE SIDE OF
        THE UNIT PREVENTING IT FROM CLOSING- per
        the technicin that did the showthru on
        the unit- he was having issues getting
        the latches to latch- technician was
        cody
        CAUSE:        COMPARTMENT DOOR IS BOWED **NEED MORE
        INFO, MEASUREMENTS AND/OR TAG FROM DOOR
        FRAME.**
2        CMR TRIED TO HOOK UP THE STABALIZER ARMS FOR THE      E    17249    POWER
        HITCH AND COULD NOT GET THEM TO HOOK UP. WOULD LIKE
```

Continued on page 2

Work Order : 10172B

 Job # Description JOB INFORMATION Type Bill To

 LOOKED AT

 Job # Part No Description PARTS Bill to Qty Price Total

 WARR0 146878 NOVAFLEX SEALANT TRANSLUCEN W-1021 2 8.98 17.96
 WARR0 822051663 DECAL, PUMA, ULTRA LITE LEG W-1021 1 10.56 10.56
 1 82209720 DOOR, COMPARTMENT, 30" X 17 W-1021 1 67.69 67.69

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 ARR01 Z992 MISC LABOUR CODE (WARR RW W-1021 0.00 115.00 0.00
 ARR01 Z992 MISC LABOUR CODE (WARR RW W-1021 2.00 115.00 230.00
 ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 0.50 115.00 57.50
 1 WARR MANUFACTURER WARRANTY JGK W-1021 0.50 115.00 57.50

 Job # Excode Description EXTRAS bill to Qty Price Total

 ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00
 ARR01 FRT FREIGHT W-1021 1.00 38.55 38.55

 BILLINGS SUMMARY
 Type Bill Id Parts Labour Sublet Extras Tax Total

 W 1021 96.21 345.00 0.00 38.55 0.00 479.76
 Totals 96.21 345.00 0.00 38.55 0.00 479.76

&k2S
 &k0S