



Warranty Claim Form

Date: 6/13/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT2523R8830618
Transcend 200MK
Retail Purchase Date: null
Work Started: 5/13/2024
Work Completed: 5/13/2024

Claim Status: Paid
Dealer Work Order #: 10181B
Unit Offline Date: 2/20/2024

Claim #: 808011
Labor: \$115.00
Parts: \$58.35
Shipping: \$12.44
Total: \$185.79

Notes: JH 6/3 Placed in Pending per dealer request. JH 3/20 590062 Do not replace decals use heat gun to remove bubbles.

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Operation Line # 1

Flat Rate Code: 560037 Baggage - Adjust - Non Slam Latch *Fault Code:* Improper Installation/Build

Problem: Front DS compartment door will not lock

Hours: .5

Cause: I tried locking the storage door and the key only turns a small amount and will not fully engage. The lock latch is striking the door frame.

Amount: 57.50

Remedy: I adjusted the lock latch by flipping it around. Verified the lock does engage. *Job took longer than expected

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 590062 Decals - Remove Air Bubbles

Fault Code: Improper Installation/Build

Problem: Multiple bubbles in front decals

Hours: .5

Cause: Caused from installation

Amount: 57.50

Remedy: Need new decals ordered *Job took longer than expected

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
530213 DIE CUT TRANSCEND LG TRANSCEND LEGEND	DIE CUT TRANSCEND LG TRANSCEND LEGEND		1	1	26.21
530214 DIE CUT TRANSCEND FRONT #6	DIE CUT TRANSCEND FRONT #6		1	1	24.93
530219 DIE CUT TRANSCEND FRONT #32 LH	DIE CUT TRANSCEND FRONT #32 LH		1	1	7.21