



Warranty Claim Form

Date: 6/19/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FS3626PAA15181
Solitude 310GK-R
Retail Purchase Date: 2/24/2023
Work Started: 3/27/2024
Work Completed: 3/27/2024

Claim Status: Paid
Dealer Work Order #: 10209
Unit Offline Date: 2/15/2023

Claim #: 810922
Labor: \$57.50
Parts: \$0.00
Shipping: \$0.00
Total: \$57.50

Notes: hk 06/12-Repair only 910039 - Curt Axle U-Bolt Torque 23V-490/2023-395

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

John A Race
14561 S Appaloosa Ln
Homer Glen, Illinois 60491-8304
United States
708-491-5375

Operation Line # 1

Flat Rate Code: 710078 Air Conditioning - R & R Capacitor *Fault Code:* Damaged/Maintenance

Problem: Customer states rear AC is making abnormal noises.

Hours: .5

Cause: AC fan is contacting shroud on condensor coil. Two plastic pieces are rubbing,

Amount: 57.50

Remedy: Adjustments to position of fan made. Also added washer under shroud screws to elevate. No longer contacts, tested ok.

Sublet Repairs: \$0.00

Manufacturer #: AIRXCEL

Model #: 48254-669

Serial #: 220460166