

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 10211

Date In:	22 MAR 24	Author:	KOTT
Promised Date:	17 APR 24	Stock No:	11001
:	:	Year:	2024
Customer Name:	17264 - DUMKE, CHRISTI	Manufacturer:	FOREST RIVER
Address:	8120 GROVE AVE	Brand:	FLAGSTAFF MICRO-LITE
:	WISCONSIN RAPIDS, WI	Model:	21FBRS
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	7154671208	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	CHRISDUMKE2026@GMAIL.C	Tag#:	PU@ST- 4/17@2
Purchased Date:	18 MAR 24	:	:
Delivery Date:	17 APR 24	:	:
InService Date:	:	:	:
Serial#:	4X4TFLW26RD457305	:	:

Job #	Description	JOB INFORMATION	Type	Bill To		

1	TOW: 2017 DODGE RAM 2500 BC: Y TP: Y HITCH: REESE		I	DO	DEALE	
PDIT	COMPLAINT: SOLD FINISH PREP TRAVEL TRAILER		I	PDI	PRE-D	
	CAUSE: Finish prep needed					
	CORRECTION: 2 30s and battery installed					
ST	COMPLAINT: SHOWTHRU- SALESMAN:MARK		I	PDI	PRE-D	
	CAUSE: Showthru needed					
	CORRECTION: Complete					
CIN	COMPLAINT: CLEAN INTERIOR- NEW		I	PDI	PRE-D	
	CAUSE: NEED CLEAN					
	CORRECTION: CLEANED					
CEN	COMPLAINT: CLEAN EXTERIOR- NEW		I	PDI	PRE-D	
	CAUSE: Wash needed					
	CORRECTION: Complete					
2	COMPLAINT: THE BUMPER ON THE REAR OF THE UNIT HAS RUST ON IT- NEEDS TO BE REPAIRED (PAINTED)		W	1021	FORES	
	CAUSE: Bumper has rust on it					
	CORRECTION: Matt had me take a dee a sander with 320 sand paper to take all the rust off and make it smooth and to remove all the rust then cleaned off with brake parts cleaner taped off the back with cardboard and painted the whole back bumper with black paint					
MF30	COMPLAINT: MOUSE FREE- 21-30 FEET		I	DOF	DEALE	
	CAUSE: NEED MOUSE FREE					
	CORRECTION: APPLIED MOUSE FREE					
ISR0	COMPLAINT: INTERNAL STOCK REPAIR 03		E	17264	DUMKE	

Continued on page 2

Work Order : 10211

 Job # Description JOB INFORMATION Type Bill To

 CAUSE: Clearance light not working
 CORRECTION: Light tested on 12 v no operation,
 replaced with new

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
PDITT	840821034507	12V 24 MDP BATTERY		I-PDI	1	85.20	85.20
MF30	51700005	MOUSE FREE (5GAL BULK)	P	I-DOF	30	4.10	123.00
CIN	019079236326	TOILET TISSUE, SGL. 2 PL		I-PDI	1	1.02	1.02
CIN	014717396042	HTS STANDARD 10' SEWER H		I-PDI	1	5.89	5.89
CIN	019079900142	PARK ADAPTER BULK 30-15		I-PDI	1	3.34	3.34
ISR03	822071312	RED MARKER LIGHT		E-17264	1	6.26	6.26

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
PDITT	RV1F-3B	SOLD FINISH PREP TRAVE	DL		I-PDI	0.50	70.00	35.00
	ST RV1D-3	SHOW THRU & PICK UP PD	DL		I-PDI	0.81	70.00	56.70
	CIN CI	CLEAN INTERIOR			I-PDI	0.00	70.00	0.00
	CEN CE	CLEAN EXTERIOR	DL		I-PDI	0.53	70.00	37.10
	2 WARR	MANUFACTURER WARRANTY	CF	W-1021		0.00	115.00	0.00
	MF30 Z991	APPLY MOUSE FREE	JT	I-DOF		0.00	70.00	0.00
	2 WARR	MANUFACTURER WARRANTY	CF	W-1021		0.50	115.00	57.50
ISR03	Z991	MISC LABOUR CODE (INTE	DL	E-17264		0.50	130.00	65.00
	ST RV1D-3	SHOW THRU & PICK UP PD	DL		I-PDI	1.19	70.00	83.30

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
PDITT	LP	PROPANE		I-PDI	40.00	1.41	56.40
ISR03	SSE	SHOP SUPPLIES - EXTERNAL		E-17264	1.00	4.88	4.88

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	17264	6.26	65.00	0.00	4.88	4.22	80.36
I	DOF	123.00	0.00	0.00	0.00	0.00	123.00
I	PDI	95.45	212.10	0.00	56.40	0.00	363.95
W	1021	0.00	57.50	0.00	0.00	0.00	57.50
Totals		224.71	334.60	0.00	61.28	4.22	624.81

&k2S
 &k0S