



Warranty Claim Form

Date: 3/21/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR4327R9925493

Reflection 370FLS

Retail Purchase Date: 12/9/2023

Work Started: 3/4/2025

Work Completed: 3/4/2025

Claim Status: Paid

Dealer Work Order #: 10273

Unit Offline Date: 11/14/2023

Claim #: 881106

Labor: \$230.00

Parts: \$13.62

Shipping: \$2.33

Total: \$245.95

Notes: this is from pre auth. 818808 that didn't get paid for-see Amanda B.3/14/24.

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

GREGORY ZUEHLKE
3665 GOLDEN EAGLE DR
BELOIT, Wisconsin 53511
United States
608-449-9498

Operation Line # 1

Flat Rate Code: 120024 Hub - R&R - Axle Hub Grease Dust *Fault Code:* Component Failure
Cap

Problem: Customer stated that one of the tires on the door side of the unit, the bearing buddy
came off and need to be put back on.

Hours: 2

Cause: Will need four new bearing buddies.

Amount: 230.00

Remedy: Need four new bearing buddies and 2 hours of labor.

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		2	1	0.00
120018 AXLE DUST CAP ONLY FOR 52 - 6 K	AXLE DUST CAP ONLY FOR 52 - 6 K		4	1	8.53
120019 AXLE RUBBER PLUG UNIVERSAL W LCI LOGO	AXLE RUBBER PLUG UNIVERSAL W LCI LOGO		4	1	5.09