

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	1894457
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4FFLE24P1904372
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$115.00	SITE/WAREHOUSE	010 / 010C
OWNER INFORMATION		ITEM #	FLF524BBS
		DEALER RO #	10287
		CLAIM START DATE	04/24/2024
		CLAIM END DATE	06/03/2024

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-100-01-00-001035	Cabinet Door - Interior/Cabinetry/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-04-24 10:19:44 :: Complaint: Rear cabinet door above stove is broken. Cause: Broke apart from manufacturer not glueing edges well enough. Correction: R & R cabinet door. Additional Note : greeneway@dealer-advisors.com, 2024-04-24 10:20:48 :: Door measurements are 28" wide by 9 3/4" tall			
	Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$57.50
	Serial#	Appr Hrs	0.40	Appr Labor Amt \$46.00
	Notes			

Part

Line# 2	Item #	Description		
	F100345241	CABINET DOOR - SOP: SQUARE - NEWPORT ASH - 28" X 9.75" - V# 609101 X		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$51.88
	Appr Qty	1.00	Sub Freight	\$19.48
			Appr Dlr Price	\$51.88
			Appr Freight	\$19.48
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	20-73-01-00-000739	Fenderskirt - Exterior/Fender Skirts, Wheel Well/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-05-01 07:55:02 :: Complaint: Fender skirt on door side of the unit is cracked. Cause: Fender skirt was cracked from factory. Correction: Replace fenderskirt.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$34.50	
Serial#	Appr Hrs	0.30	Appr Labor Amt \$34.50	
	Notes			

Part

Line# 1	Item #	Description		
	F100146066	FENDER SKIRT - PFL: TANDEM - GUNSMOKE - V# TS19-18C20019GS X		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$51.03
	Appr Qty	1.00	Sub Freight	\$32.60
			Appr Dlr Price	\$51.03
			Appr Freight	\$32.60
	Notes			

Submitted	Labor Amt	\$92.00
	Parts & Freight	\$154.99
	Total	\$246.99

Approved	Labor Amt	\$80.50
	Parts & Freight	\$154.99
	Total	\$235.49

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	