



Warranty Claim Form

Date: 6/13/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE1812R7701928

Imagine 14MS

Retail Purchase Date: null

Work Started: 6/4/2024

Work Completed: 6/4/2024

Claim Status: Paid

Dealer Work Order #: 10292

Unit Offline Date: 12/6/2023

Claim #: 807972

Labor: \$57.50

Parts: \$17.91

Shipping: \$12.44

Total: \$87.85

Notes: JS 04/16/24 510008 - damaged - professional courtesy extended to dealer to replace, as requested.

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

Operation Line # 1

Flat Rate Code: 510008 Decals - R&R Sidewall Decal/Logo/Die Fault Code: Damaged/Maintenance
Cut

Problem: Decal front ODS corner is bad and needs replacement.

Hours: .5

Cause: Damaged decal needs black decal replaced.

Amount: 57.50

Remedy: DAMAGED DECAL NEEDS BLACK DECAL REPLACED (NOT ON DAF UNSURE
HOW IT HAPPENED SD)

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	0.00
511775 DIE CUT SIDE #14 LH IMAGINE 2022	DIE CUT SIDE #14 LH IMAGINE 2022		1	1	17.91