

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497		CLAIM STATUS Paid	
GREENEWAY INC		CLAIM 1919987	
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN WEB	
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN 4X4TCRS21NS231549	
USA		CHASSIS VIN	
		MILEAGE 0	
Labor rate: \$115.00		SITE/WAREHOUSE 020 / 020	
OWNER INFORMATION		ITEM # CRT40CCK	
LESTER LAUB		DEALER RO # 10369	
PO BOX 223		CLAIM START DATE 05/16/2024	
King, WI 54946		CLAIM END DATE 05/30/2024	
USA			
Retail Date of Purchase 05/30/2023		WARRANTY EXPIRATION DATE 05/30/2024	

Claim Line Details

Labor					
Line# 1	Operation Code	Operational Description			
	60-138-01-00-001527	Termination Valve Cable with Removal Of Underbelly - Plumbing/Drainage System/Replace/No Tread Code			
Complaint, Cause, Correction					
Original Note : greeneway@dealer-advisors.com, 2024-05-16 10:03:33 :: Complaint: Customer called stating the black gate valve is stuck. Customer stated when left unit in the fall, the handle was fine, and we winterized the unit. Cause: Black tank cable rod was bent and wasn't allowing to open or close the valve onto tank. Correction: Lowered underbelly and disconnected the cable from the black tank and pulled cable from hanger. Installed new black tank cable and secured up underbelly.					
Model#		Dlr Sub Hrs	1.00	Sub Labor Amt	\$115.00
Serial#		Appr Hrs	1.00	Appr Labor Amt	\$115.00
Notes					
AUTHORIZED					
Part					
Line# 1	Item #	Description			
	60P10689A	TERMINATION VALVE, 3", W/ 96" CABLE ATTACHED [EB6] 2010- CEDAR CREEK 203663- : SILVERBACK 203916- MOVED TO DOCK STATION			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$57.51	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$57.51	Appr Freight \$0.00
Notes					

Submitted	Labor Amt	\$115.00	Approved	Labor Amt	\$115.00
	Parts & Freight	\$57.51		Parts & Freight	\$57.51
	Total	\$172.51		Total	\$172.51

DEALER	DATE	CUSTOMER	DATE
SIGNATURE		SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.		All repairs described have been inspected and are satisfactory.	