

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10468

Date In:	11 MAY 24	Author:	MGRAY
Promised Date:	11 MAY 24	Stock No:	10507C
:	:	Year:	2021
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	OZARK
:	CHICAGO, IL	Model:	2500THX
Postal/Zip:	60673-1218	Miles/Hrs:	:
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TTH-TT TOY HAULER
Cell Phone:	:	License#:	129177RV
Email:	NONE	Tag#:	DROPPED UNIT 5/11
Purchased Date:	08 JUL 23	:	:
Delivery Date:	25 JUL 23	:	:
InService Date:	:	:	:
Serial#:	5ZT2ZKPB0MG401741	:	:

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT: Recall on fresh tank falling out. RECALL W    1021    FORES
      #22V729 ATTACHED TO WO - DROPPED OFF
      5/11
      CAUSE: Recall inspection on possible fresh tank
      dislodgement - Its understandable why
      this recall happened, the nylon straps
      holding the tank in place are not rated
      to hold a full tank while moving down
      the road. This RV needs the remedy
      kit. 2 hours to drop and move
      underbelly pan style membrane, install
      three straps above the axles with
      minimal clearance to work. Difficult
      area to maneuver in.
      CORRECTION: Kit received. No instructions, fasteners
      are humorously subpar to do the job. We
      could have come up with a better
      solution ourselves. Used some real
      screws to get the problem fixed
      correctly. Three metal straps evenly
      placed under fresh tank and fastened
      with 3/8" self-tapping hex screws, far
      enough away to not puncture tank.
SUM    COMPLAINT: SUMMERIZE CAMPER AND DEWINTERIZE            E    16953    KLADE
      CAUSE: Summarize 1, seasonal change
      CORRECTION: Flushed out all faucets on city
      connection, aligned water heater valving
      so not bypassed anymore, put in anode
```

Continued on page 2

Work Order : 10468

 Job # Description JOB INFORMATION Type Bill To

 plug. Summarized

 Job # Part No Description PARTS Bill to Qty Price Total

 1 82202078 RECALL REMEDY KIT22V729 W-1021 1 0.00 0.00

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 1 Z992 MISC LABOUR CODE (WARR RW W-1021 0.70 115.00 80.50
 SUM Z990 SUMMERIZE RW E-16953 0.00 130.00 0.00
 1 Z992 MISC LABOUR CODE (WARR RW W-1021 0.60 115.00 69.00
 1 Z992 MISC LABOUR CODE (WARR RW W-1021 0.30 115.00 34.50
 SUM Z990 SUMMERIZE RW E-16953 0.50 130.00 65.00
 1 Z992 MISC LABOUR CODE (WARR RW W-1021 0.40 115.00 46.00

 Job # Excode Description EXTRAS bill to Qty Price Total

 1 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 4.88 4.88
 SUM J-ADJ QUOTE ADJUSTMENT E-16953 1.00 -10.00 -10.00

 BILLINGS SUMMARY
 Type Bill Id Parts Labour Sublet Extras Tax Total

 E 16953 0.00 65.00 0.00 -10.00 3.03 58.03
 W 1021 0.00 230.00 0.00 4.88 0.00 234.88

 Totals 0.00 295.00 0.00 -5.12 3.03 292.91

&k2S
 &k0S