

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	1920932
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2ZKPB0MG401741
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	072 / 072F
		ITEM #	ZKT2500TH-72
		DEALER RO #	10468
		CLAIM START DATE	05/16/2024
		CLAIM END DATE	06/04/2024
Labor rate:	\$115.00		
OWNER INFORMATION			
JEAN FLESHER			
2502 15TH PL			
Kenosha, WI 53140			
USA			
Retail Date of Purchase	07/03/2021	WARRANTY EXPIRATION DATE	07/03/2022

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	RC-672-03-00-004252	22V729, 2022-556 - HOLDING TANKS - INSPECTION AND REPAIR - Recall/Water Tank/Install/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-05-16 15:54:25 :: Complaint: Recall on freshwater tank. #22V729 Cause: Recall on freshwater tank. #22V729 Correction: Recall inspection; needs repair with remedy kit. 2 hours to drop and move underbelly pan style membrane, install three straps above the axles. Kit was received with no instructions. Used screws from the shop that were more up to par than the ones in the kit to secure it more properly. Please three metal straps evenly under the fresh tank and fastened with 3/8" self-tapping hex screws far enough away to not puncture the tank.			
Model#	Dlr Sub Hrs	2.00	Sub Labor Amt	\$230.00
Serial#	Appr Hrs	2.00	Appr Labor Amt	\$230.00
	Notes			
	Authorized.			

Part

Line# 1	Item #	Description				
	USERPART	Longer screws				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$4.88	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$4.88	Appr Freight	\$0.00
	Notes					

Submitted	Labor Amt	\$230.00	Approved	Labor Amt	\$230.00
	Parts & Freight	\$4.88		Parts & Freight	\$4.88
	Total	\$234.88		Total	\$234.88

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	