

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10516

Date In:	21 MAY 24	Author:	MGRAY
Promised Date:	28 MAY 24	Stock No:	11096
:	:	Year:	2023
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA TT
:	: CHICAGO, IL	Model:	24FBSC
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	db 5/23 - updated cmr
Purchased Date:	04 MAR 24	:	:
Delivery Date:	12 MAR 24	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUNB7P4018079	:	:

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
WARR COMPLAINT: AFTER ADDITIONAL SEAL PLACE, IN HARD W 1021 FORES  
LARGE AMOUNT OF STILL LEAKING.  
RECOMMENDING WIDE GUTTER WITH SPOUTS ON  
UNIT. WATER IS BUILDING UP TO FAST  
CAUSING LEAK TO CONTINUE INTO INTERIOR  
OF UNIT. GUTTER WITH SPOUT WILL PREVENT  
BUILD-UP OF WATER CAUSING LEAK AND SPOUT  
WILL DETER EXSESSIVE AMOUNTS OF WATER  
FROM RUNNING DOWN UNIT.  
CAUSE: Water leaking into unit after a heavy  
rain at the top of slide seal ods.  
CORRECTION: Had to reseal the top of the dseal area  
to prevent water getting behind the  
mounting strip. Tested good.

\*\*\*\*\*  
Job # Part No Description PARTS Bill to Qty Price Total  
\*\*\*\*\*  
WARR 82200111 TRIM METAL 16' ET INSERT GU W-1021 0 66.01 0.00  
WARR 822000364 GUTTER SPOUT LONG L&R BLACK W-1021 0 1.87 0.00

\*\*\*\*\*  
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total  
\*\*\*\*\*  
WARR RV30G-3 MOLDING R&R FLAT\ /CORN TD W-1021 1.00 115.00 115.00

Continued on page 2

Work Order : 10516

\*\*\*\*\*

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	0.00	115.00	0.00	0.00	0.00	115.00
	Totals	0.00	115.00	0.00	0.00	0.00	115.00

&k2S  
&k0S