



Warranty Claim Form

Date: 7/18/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2926R3439562
Imagine 24BSE
Retail Purchase Date: null
Work Started: 7/2/2024
Work Completed: 7/2/2024

Claim Status: Paid
Dealer Work Order #: 10529B
Unit Offline Date: 5/15/2024

Claim #: 818479
Labor: \$80.50
Parts: \$0.00
Shipping: \$0.00
Total: \$80.50

Notes: JH 7/9 Placed in pending per dealer request.

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Operation Line # 1

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) *Fault Code:* Improper Installation/Build

Problem: Trim next to bed is loose and lifting from the wall.

Hours: .2

Cause: Not stapled in place to secure.

Amount: 23.00

Remedy: Nailed into place.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) *Fault Code:* Damaged/Maintenance

Problem: Batten trim above bed has a rip in finish.

Hours: .5

Cause: Peel seam tape and it looks like it was repaired once already and repair failed.

Amount: 57.50

Remedy: Reoved and cleaned old repair, used a touch of glue and putty to cover.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: