



8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

[spreading the joy of the camping lifestyle]

[715] 325-5170
mail@greenwayrv.com
www.greenwayrv.com

W/O: 10552
Promised Date:
06 JUN 24



WO #: 10552

Customer Name: 17140 - MORSETH-MAYER,
MARK

Address: 513 W 12TH STREET
MARSHFIELD, WI

Postal/Zip: 54449

Phone#(res): 715-305-3430

Phone#(bus):

Cell Phone:

Email:

Date In: 28 MAY 24
Promised Date: 06 JUN 24

Purchased Date: 18 OCT 23

Delivery Date: 18 APR 24

InService Date:

Serial#: 573FR362XN9918490

Author: TPASSER

Stock No: 10500

Year: 2022

Manufacturer: GRAND DESIGN

Brand: REFLECTION FW

Model: 320MKS

Miles/Hrs: 0

Exterior Color:

Unit Type: FW-FIFTH WHEEL

License#:

Tag#:

Job #SC - Internal

SERVICE CALL TO DELLS/ SHANGRI-LA SITE 47

Labor

Job #	Description	Total
SC	SERVICE CHARGE	N/C

Other Services

Code	Description	Qty	Price	Total
SC	SERVICE CALL	1.00	N/C	N/C
SSE	SHOP SUPPLIES - EXTERNAL	1.00	N/C	N/C

Subtotal for Job #SC: 0.00

Job #1 - Warranty

COMPLAINT: CMR CALLED STATING REFER WORKING INTERMITTENTLY - HOT DOGS FREEZING THEN UNTHAWING ETC. BATTERY TERMINALS FOUND LOOSE - CMR FEELS CONVERTER ISSUE -PLEASE BRING ALONG

CAUSE: pics taken I checked voltage going to refrigerator control module on top of refrigerator is 13.46 good checked voltage down at 12 volt compressor is 13.40 the compressor is not working will need a complete refrigerator

CORRECTION: Will need a complete refrigerator.....

Labor

Job #	Description	Total
1	MULTIPLE LABOR CODES	57.50

Subtotal for Job #1: 57.50

Job #2 - External

COMPLAINT: 6/3 CMR CALLED REQUESTING HAVING CAMCO COVER INSTALLED ON ALL 3 VENTS OF UNIT - WHITE

CAUSE: install 2 camco covers not three the third one is a max air vent with rain sensor used three tubes of dicor

CORRECTION: after install of two camco covers the customer wanted me to remove the cable dish from the roof and reconnect antenna the tv now works

Customer #: 17140
MORSETH-MAYER, MARK



W/O: 10552
Promised Date: 06 JUN 24

Labor		Total
Job #	Description	N/C
2	MULTIPLE LABOR CODES	

Parts				
Part #	Description	Qty	Price	Total
014717404410	CAMCO ROOF VENT COVER - WHITE	2.00	N/C	N/C
677917000333	10.3oz TUBE LAP SEALANT W	3.00	N/C	N/C

Subtotal for Job #2: 0.00

Parts Total: 0.00
Labour Total: 57.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 57.50

CUSTOMERS CLEAR RECEIPT

The above described property has been received, and after having examined the work done, the material furnished, both the work and material has been found to be satisfactory.
I agree that any goodwill repairs are in no way an admission that the vehicle suffers from any defect or issue, or that the repair should be covered under warranty.

Customer Signature : _____

Date: 10 Jun 2024



Customer #: 17140
MORSETH-MAYER, MARK

