

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10556B

|                 |                     |                 |                       |
|-----------------|---------------------|-----------------|-----------------------|
| Date In:        | 03 JUN 24           | Author:         | AFREEMAN              |
| Promised Date:  | 05 JUN 24           | Stock No:       | 11039                 |
| :               | :                   | Year:           | 2024                  |
| Customer Name:  | 17347 - DEAN, CHAD  | Manufacturer:   | GRAND DESIGN          |
| Address:        | 3954 GREEN BRIAR CT | Brand:          | REFLECTION 100 SERIES |
| :               | NEKOOSA, WI         | Model:          | 27BH                  |
| Postal/Zip:     | 54457               | Miles/Hrs:      | 0                     |
| Phone#(res):    | 7156976449          | Exterior Color: |                       |
| Phone#(bus):    |                     | Unit Type:      | FW-FIFTH WHEEL        |
| Cell Phone:     |                     | License#:       |                       |
| Email:          | ldrski45@gmail.com  | Tag#:           | PU@ST 6/5@2pm         |
| Purchased Date: | 25 MAY 24           | :               | :                     |
| Delivery Date:  | 05 JUN 24           | :               | :                     |
| InService Date: |                     | :               | :                     |
| Serial#:        | 573FR3325R3348802   | :               | :                     |

\*\*\*\*\*

| Job # | Description                                                                                                                                                                                                                                                                                                                                                                                       | JOB INFORMATION | Type | Bill To    |
|-------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|------|------------|
| 4     | COMPLAINT: WATER STAINS FOUND UNDER MATTRESS IN MASTER BEDROOM.<br>CAUSE: UNSURE OF HOW MOISTURE GOT INTO THE UNIT. WILL CHECK FOR LEAKS. WILL NEED .20 TO CLEAN STAIN WITH BLEACH AND CHECK FOR LEAKS IN UNIT.<br>CORRECTION: WASH MOLD STAINS WITH BLEACH WATER AND LET DRY.                                                                                                                    |                 | W    | 1020 GRAND |
| 5     | COMPLAINT: STOVE GLASS TOP IS MISSING HALF OF THE TOP. MISSED ON DAF, NO SIGNS OF BROKEN GLASS IN UNIT.<br>CAUSE: UNIT DID NOT HAVE SECOND HALF OF OVEN TOP. CAME FROM MFG LIKE THIS. NO SIGNS OF BROKEN GLASS IN UNIT. NEED PIC OF STOVE LABEL. NEED .2 HRS FOR REMOVAL AND REPLACING STOVE TOP AND PART # 721292 PLEASE.<br>CORRECTION: WILL NEED TO REPLACE THE GLASS STOVE TOP ONLY ON STOVE. |                 | W    | 1020 GRAND |

\*\*\*\*\*

| BILLINGS SUMMARY |       |        |        |        |      |       |
|------------------|-------|--------|--------|--------|------|-------|
| Type Bill Id     | Parts | Labour | Sublet | Extras | Tax  | Total |
| *****            |       |        |        |        |      |       |
| Totals           | 0.00  | 0.00   | 0.00   | 0.00   | 0.00 | 0.00  |

Continued on page 2

Work Order : 10556B

&k2S  
&k0S