



Warranty Claim Form

Date: 7/18/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3325R3348802

Reflection 27BH

Retail Purchase Date: 6/5/2024

Work Started: 7/6/2024

Work Completed: 7/6/2024

Claim Status: Paid

Dealer Work Order #: 10556B

Unit Offline Date: 12/4/2023

Claim #: 818422

Labor: \$57.50

Parts: \$293.58

Shipping: \$26.90

Total: \$377.98

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

3954 GREEN BRIAR CT
NEKOOSA, Wisconsin 54457
United States
715-697-6449

Operation Line # 1

Flat Rate Code: 650030 Bed Base - Repair Base

Fault Code: Improper Installation/Build

Problem: Water stains found under mattress in master bedroom.

Hours: .3

Cause: Unsure how moisture got into the unit, will need to check for leaks.

Amount: 34.50

Remedy: Need to clean the mold stain with bleach water and let dry. *Unsure on labor code for this.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 720119 Range/Oven - R & R Range Cover

Fault Code: Improper Installation/Build

Problem: Stove glass top is missing half of the top, this was missed on the DAF.

Hours: .2

Cause: No signs of broken glass in the unit, unit did not have second half of oven top when coming from the manufacturer.

Amount: 23.00

Remedy: Will need to R&R stove top part #721292

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
721292 RANGE OVEN TOP GLASS TRAY MODULE ONLY BLACK F/ FGR21G3A2-BG (FURRIION C-FGR17G3A1-028)	RANGE OVEN TOP GLASS TRAY MODULE ONLY BLACK F/ FGR21G3A2-BG (FURRIION C-FGR17G3A1-028)		1	1	293.58