



8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

(715) 325-5170
mail@greenewayrv.com
www.greenewayrv.com

[spreading the joy of the camping lifestyle]

W/O: 10622
Promised Date:
45 JUN 24



WO #: 10622 (Appointment Date: 10 JUN 2024 - Time: 08:00am)

Customer Name: 17278 - HILDEBRANDT,
CARRIE

Address: W1205 NENNO RD
MAYVILLE, WI

Postal/Zip: 53050

Phone#(res): 920-212-0431

Phone#(bus):

Cell Phone:

Email: OBGIRL@GMAIL.COM

Date In: 10 JUN 24

Promised Date: 15 JUN 24

Purchased Date: 04 APR 24

Delivery Date: 19 APR 24

InService Date:

Serial#: 573TE2018R7702048

Author: KOTT

Stock No: 11070

Year: 2024

Manufacturer: GRAND DESIGN

Brand: IMAGINE AIM

Model: 15RB

Miles/Hrs:

Exterior Color:

Unit Type: TT-TRAVEL TRAILER

License#:

Tag#:

Job #WARR01 - Warranty

COMPLAINT: WARRANTY REPAIR 1 - CUSTOMER STATES THAT THE CLOSET DOOR TO THE LEFT OF THE MURPHY BED- IF YOU ARE STANDING IN FRONT OF IT AND LOOKING AT IT- SCRAPES THE CEILING

CAUSE: Cabinet door adjustment

CORRECTION: Adjusted European hinges on cabinet door left side of bed to clear ceiling. Tested good.

Labor

Job #	Description	Total
WARR01	MISC LABOUR CODE (WARRANTY)	11.50

Subtotal for Job #WARR01: 11.50

Job #WARR02 - Warranty

COMPLAINT: WARRANTY REPAIR 2 - CUSTOMER STATES THAT THERE IS A LEAK BY THE BLACK WATER- CUSTOMER STATES THAT THERE IS A HOSE THAT COMES DOWN FROM THAT AREA AND IT IS DRIPPING WATER-

CAUSE: Check black tank for leak.

CORRECTION: Filled black tank up to 2/3 full and wait for it to leak. Also filled Grey tank. Couldn't reproduce leak at this time.

Labor

Job #	Description	Total
WARR02	MISC LABOUR CODE (WARRANTY)	58.65

Subtotal for Job #WARR02: 58.65

Job #WARR03 - Warranty

COMPLAINT: WARRANTY REPAIR 3 - CUSTOMER STATES THAT THE KITCHEN SINK IS LEAKING- UNDERNEATH INTO THE CABINET-

CAUSE: Check for leak under kitchen sink.

CORRECTION: Pressurized system with water. I moved the water lines around to see if the lines would leak. No leak as of yet. Turned faucet on to see if the drain had a leak and found none. No leaks at this time.

Customer #: 17278
HILDEBRANDT, CARRIE



W/O: 10622
Promised Date: 15 JUN 24



Customer #: 17278
HILDEBRANDT, CARRIE



Labor		
Job #	Description	Total
WARR03	MISC LABOUR CODE (WARRANTY)	11.50
Subtotal for Job #WARR03:		11.50

Job #WARR04 - Warranty

COMPLAINT: WARRANTY REPAIR 4 - BEDROOM LEFT NIGHT STAND - BOTTOM DRAWER NOT OPERATING CORRECT - CMR WILL MARK W/ POST-IT.

CAUSE: Drawer left side of Murphy bed is out of track.

CORRECTION: Reinstall drawer glide in track. Tested good.

Labor		
Job #	Description	Total
WARR04	MISC LABOUR CODE (WARRANTY)	11.50
Subtotal for Job #WARR04:		11.50

Job #1 - External

FRONT JACK RUBBER PLUG WAS LOST BY CMR, PLEASE REPLACE

Parts				
Part #	Description	Qty	Price	Total
82206570	TONGUE JACK, RUBBER PLUG ONLY, FOR POWER TONGUE JACK	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Parts Total:	0.00
Labour Total:	93.15
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	93.15

CUSTOMERS CLEAR RECEIPT

The above described property has been received, and after having examined the work done, the material furnished, both the work and material has been found to be satisfactory.
I agree that any goodwill repairs are in no way an admission that the vehicle suffers from any defect or issue, or that the repair should be covered under warranty.

Customer Signature : _____

Date: 12 Jun 2024

