



Warranty Claim Form

Date: 10/30/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TR3827P3346770
Reflection 315RLTS
Retail Purchase Date: 10/31/2023
Work Started: 10/10/2024
Work Completed: 10/10/2024

Claim Status: Paid
Dealer Work Order #: 10673
Unit Offline Date: 5/2/2023

Claim #: 845963
Labor: \$34.50
Parts: \$0.00
Shipping: \$0.00
Total: \$34.50

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

CHERYLL ANN KWASNY
6801 RUNNING HORSE RD
RACINE, Wisconsin 53402
United States
262-994-8014

Operation Line # 1

Flat Rate Code: 590039 Roof Vents - R&R Lid

Fault Code: Damaged/Maintenance

Problem: Vent in the bathroom is not closing tight. Seems like it is stripped.

Hours: .3

Cause: Clip too tight.

Amount: 34.50

Remedy: Clip that holds vent lid centered was too tight, not allowing lid to close completely. Bent out wings on clip slightly and it is closing fine now *unsure on labor code- no vent repair code* *Sublet Repairs:* \$0.00

Manufacturer #:

Model #:

Serial #: