

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10719

Date In: 27 JUN 24 Author: MGRAY
Promised Date: 05 JUL 24 Stock No: 10450
: Year: 2022
Customer Name: 1852 - FOSNAUGH, GENE Manufacturer: FOREST RIVER
Address: 2001 RIVERVIEW AVE, LO Brand: FLAGSTAFF E-PRO
: STEVENS POINT, WI Model: E19FDS
Postal/Zip: 54481 Miles/Hrs:
Phone#(res): 715-310-6114 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: 715-310-6116 License#:
Email: GENEFOSSNAUGH@YAHOO.COM Tag#: CALLED 6/28 - UNIT COM
Purchased Date: 27 FEB 24 :
Delivery Date: 21 MAR 24 :
InService Date: :
Serial#: 5ZT2FSJC5N3026657 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - LOCKS ON COMPARTMENT W 1021 FORES
DOOR ARE NOT EASY TO OPEN. ONE HAS A
BROKEN KEY IN IT. WILL TAPE ALL DOORS
WITH ISSUES.
CAUSE: Compartment door latch adjustment. NEED
.50 FOR REPAIR
CORRECTION: Change a couple of Strikers on
compartment doors and adjusted the
others for smoother operation.
WARR COMPLAINT: WARRANTY REPAIR 2 - FILLED FRESH WATER W 1021 FORES
TANK AND PULLED OVER TO SITE FROM FILL
STATION. THEN THERE WAS WATER IN THE
FRONT COMPARTMENT. NOT WATER DAMAGE,.
FIRST TIME THIS HAS HAPPENED.
CAUSE: test gravity fresh water fill for leaks.
customer says they had water in front
storage after filling tank. NEED .50 FOR
REPAIR
CORRECTION: filled fresh tank completely full until
water came out of gravity fill spout.
could not produce any leaks. there is a
coffee pot in front storage that is
tipped over that maybe why they seen
water in front storage.
WARR COMPLAINT: WARRANTY REPAIR 3 - SCREEN ON WINDOW IS W 1021 FORES
NOT FLUSH WITH WINDOW. MAY NEED
ADJUSTMENT
CAUSE: Window above dinette table has a screen

Continued on page 2

Work Order : 10719

 Job # Description JOB INFORMATION Type Bill To

 adjustment to be made. WILL NEED .30 FOR
 REPAIR
 CORRECTION: Adjusted screen frame for better fit.

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 ARR01 Z992 MISC LABOUR CODE (WARR TD W-1021 0.18 115.00 20.70
 ARR02 Z992 MISC LABOUR CODE (WARR TD W-1021 0.50 115.00 57.50
 ARR03 Z992 MISC LABOUR CODE (WARR TD W-1021 0.50 115.00 57.50
 ARR01 Z992 MISC LABOUR CODE (WARR TD W-1021 0.32 115.00 36.80

 BILLINGS SUMMARY
 Type Bill Id Parts Labour Sublet Extras Tax Total

 W 1021 0.00 172.50 0.00 0.00 0.00 172.50
 Totals 0.00 172.50 0.00 0.00 0.00 172.50

&k2S
 &k0S