

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10891

Date In: 27 JUL 24 Author: MGRAY  
Promised Date: 26 JUL 24 Stock No: 10780  
: Year: 2023  
Customer Name: 1020 - GRAND DESIGN Manufacturer: GRAND DESIGN  
Address: 11333 COUNTY RD 2 Brand: IMAGINE  
: MIDDLEBURY, IN Model: 2800BH  
Postal/Zip: 46540 Miles/Hrs:  
Phone#(res): 888-825-2820 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#:  
Purchased Date: 01 APR 23 :  
Delivery Date: 11 APR 23 :  
InService Date: :  
Serial#: 573TE3225P6643913 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
1 COMPLAINT: TSB 22-004 - SKYLIGHT DAMAGED FOR TSB. W 1020 GRAND  
CAUSE: Cracked skylight.  
CORRECTION: Replaced cracked skylight. Also replaced  
cracked inner garnish and cleaned up  
water stain.  
2 COMPLAINT: water stains on the ceiling in the W 1020 GRAND  
bathroom around the skylight  
CAUSE: CLEAN UP STAIN, INSPECTED FOR WATER  
DAMAGE.  
CORRECTION: CLEANED UP STAIN, NO FURTHER WATER  
DAMAGE.

\*\*\*\*\*  
Job # Part No Description PARTS Bill to Qty Price Total  
\*\*\*\*\*  
1 677917000333 10.3oz TUBE LAP SEALANT W-1020 3 9.14 27.42  
1 630027 TRIM SKYLIGHT 14 X 22 X W-1020 0 20.23 0.00

\*\*\*\*\*  
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total  
\*\*\*\*\*  
1 RV31I-14 SHOWER SKYLIGHT DOME R TD W-1020 1.50 115.00 172.50  
2 DIAG DIAGNOSTICS TD W-1020 0.10 115.00 11.50

\*\*\*\*\*  
Job # Excode Description EXTRAS bill to Qty Price Total  
\*\*\*\*\*  
1 SSE SHOP SUPPLIES - EXTERNAL W-1020 1.00 0.00 0.00

Continued on page 2

Work Order : 10891

\*\*\*\*\*

## BILLINGS SUMMARY

| Type | Bill Id | Parts | Labour | Sublet | Extras | Tax  | Total  |
|------|---------|-------|--------|--------|--------|------|--------|
| W    | 1020    | 27.42 | 184.00 | 0.00   | 0.00   | 0.00 | 211.42 |
|      | Totals  | 27.42 | 184.00 | 0.00   | 0.00   | 0.00 | 211.42 |

&k2S  
&k0S