

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10893

Date In: 29 JUL 24 Author: MGRAY
Promised Date: 31 DEC 24 Stock No: 10292
: Year: 2022
Customer Name: 15586 - RASICO, RICKY Manufacturer: GRAND DESIGN
Address: 2936 PICKEREL LAKE ROA Brand: REFLECTION FW
: EAGLE RIVER, WI Model: 303RLS
Postal/Zip: 54521 Miles/Hrs:
Phone#(res): (262) 758-3423 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: RASICOHUGHESNET@HUGHES Tag#: emailed invoice to CMR
Purchased Date: 27 JAN 22 :
Delivery Date: 27 JAN 22 :
InService Date: :
Serial#: 573FR3429N9916393 :

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: GD CASE#00663162 Bringing unit in for W 1020 GRAND
roof damage. unit had bubbling on front
portion, air catching fabric and pulling
up. pre GD pull fabric tight and pin
back down.- GD STATES THAT IT IS A LAP
SEALANT FAILURE CMR STATES IT IS AN
ADHESIVE FAILURE.
CAUSE: Roof ballooned due to lack of
maintenance of front strip lap sealant.
Found proof of water intrusion on
plywood.
CORRECTION: In the process of gluing the fabric back
down, I found a hole in the membrane.
Not sure if it was there before or after
laying membrane back down. Customer may
want to consult his insurance. It's very
possible that it came from the roof
ballooning.
2 COMPLAINT: BRACKET ON THE SLIDEOUT, WHEEL WELL E 15586 RASIC
MOLDING IS BROKEN.
CAUSE: Screw broke off of fender skirt bracket
ods.
CORRECTION: Installed new screw.

Job # Part No Description PARTS Bill to Qty Price Total

1 677917000661 10.3oz LAP SEALANT WHITE W-1020 2 9.80 19.60

Continued on page 2

Work Order : 10893

```
*****
Job # Part No      Description      PARTS    Bill to    Qty    Price    Total
*****
1      677917000333  Dicor 501LSW-1 EPDM Self W-1020    6      9.59     57.54
1      822010718      DIE CUT DC 1 LH REFLECTI W-1020    0     97.59     0.00
1      8220591075     DIE CUT 32 LH REFLECTION W-1020    0     97.59     0.00
*****
```

```
*****
Job#  Lab Code  Description      LABOUR    Mech Bill to    Hrs    Rate    Total
*****
1  Z992      MISC LABOUR CODE (WARR TD  W-1020    0.00   115.00    0.00
1  Z992      MISC LABOUR CODE (WARR TD  W-1020    1.62   115.00   186.30
1  Z992      MISC LABOUR CODE (WARR TD  W-1020    1.78   115.00   204.70
1  Z992      MISC LABOUR CODE (WARR TD  W-1020    0.00   115.00    0.00
2  Z990      MISC LABOUR CODE (EXTE TD  E-15586   0.10   130.00    13.00
1  Z992      MISC LABOUR CODE (WARR TD  W-1020    0.50   115.00    57.50
*****
```

```
*****
Job #  Excode  Description      EXTRAS    bill to    Qty    Price    Total
*****
2  SSE      SHOP SUPPLIES - EXTERNAL  E-15586   1.00    0.98     0.98
1  FRT      FREIGHT          W-1020    1.00   12.47    12.47
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
E  15586          0.00    13.00     0.00     0.98     0.78    14.76
W  1020          77.14   448.50     0.00    12.47     0.00   538.11

Totals          77.14   461.50     0.00    13.45     0.78   552.87
*****
```

&k2S
&k0S