

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10986

Date In: 14 AUG 24 Author: MGRAY  
Promised Date: 02 SEP 24 Stock No: 11081  
: Year: 2022  
Customer Name: 118595 - YOUNG, ROGER Manufacturer: FOREST RIVER  
Address: 1004 19TH AVENUE Brand: PUMA TT  
: WISCONSIN RAPIDS, WI Model: 25RKQB  
Postal/Zip: 54494 Miles/Hrs:  
Phone#(res): 715-213-0660 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: PETERBUILTTRUCKER456@G Tag#: db 8/26 reaching out t  
Purchased Date: 29 JUN 24 :  
Delivery Date: 03 JUL 24 :  
InService Date: :  
Serial#: 5ZT2PUPB0N4015826 :

\*\*\*\*\*

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT: WHEEL BEARING ON THE ODS FRONT AXLE, WHEEL BEARING IS LOOSE. NEED REPLACEMENT, OR REPAIR. CAUSE: CMR states wheel bearing is loose. CORRECTION: Started with complaint location, front ODS axle. Jacked up tire to check for signs of loose bearing. Detected a very slight loose axle nut. Dismounted tire, removed bearing buddy, removed cotterpin, tightened axle nut one adjustment. Reinstalled cotterpin. Reinstalled bearing buddy, remounted wheel, torqued to factory specifications.		W	1021 FORES
WARR	COMPLAINT: WARRANTY REPAIR 2 - DUST CAP IS MISSING ON DS REAR AXLE. CAUSE: Missing dust cap, on bearing buddy? CORRECTION: replaced dust cap.		W	1021 FORES

\*\*\*\*\*

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
WARR0	711217012525	DUST CAP LUBED F/7K & 8K	W-1021		1	7.94	7.94

\*\*\*\*\*

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
ARR01	Z992	MISC LABOUR CODE (WARR RW	W-1021			0.22	115.00	25.30

Continued on page 2

Work Order : 10986

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR RW  W-1021    0.20   115.00   23.00
ARR01 Z992      MISC LABOUR CODE (WARR RW  W-1021    0.08   115.00    9.20
ARR01 Z992      MISC LABOUR CODE (WARR RW  W-1021    0.00   115.00    0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
W      1021          7.94     57.50     0.00     0.00     0.00     65.44
      Totals          7.94     57.50     0.00     0.00     0.00     65.44
*****
```

&k2S  
&k0S