

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10990

Date In: 14 AUG 24 Author: MGRAY
Promised Date: 14 AUG 24 Stock No: 11110
: Year: 2024
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: REFLECTION FW
: WISCONSIN RAPIDS, WI Model: 362TBS
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573FR4127R9925691 :

Job # Description JOB INFORMATION Type Bill To

WARR WARRANTY REPAIR 1 - MOLD IN UNIT WATER IS GETTING W 1020 GRAND
IN.
WARR COMPLAINT: WARRANTY REPAIR 2 - WINDOW IS LEAKING W 1020 GRAND
CAUSING MOISTURE TO GET IN THE UNIT
CAUSING THE MOLD
CAUSE: Window is leaking water coming in mold
on several one by braces and plywood bed
frame, also rusted compartment door
latches (3)WILL NEED 2 HRS TO DO ALL
REPAIRS.
CORRECTION: Emergency exit window leaking heavily
has a bend in frame of window removed
and replaced seals on window and tested,
water is coming from frame of window
where glass meets frame, need new window
ordered pics taken. Rebuilt the bed
frame, 3 one bys needed to be removed
and replaced and 2 sheets of plywood
removed and replaced, also needed new
bed, pillows, pillow cases, and blanket
all had mold.
WARR COMPLAINT: SLAM LATCHES ARE RUSTED FROM WATER W 1020 GRAND
LEAKS.
CAUSE: WILL NEED .5 HRS AND NEW SLAM LATCHES
FOR REPAIR.
WARR COMPLAINT: BEDDING WAS DAMAGED DUE TO LEAK W 1020 GRAND
CAUSE: WATER DAMAGE DUE TO FAULTY WINDOW FRAME.

Continued on page 2

Work Order : 10990

 Job # Description JOB INFORMATION Type Bill To

 CORRECTION: WILL NEED .20 AND NEW BEDDING FOR
 REPAIRS.

 Job # Part No Description PARTS Bill to Qty Price Total

 WARR0 580647 WINDOW TRIM RING ONLY 8505-8; W-1020 0 11.38 0.00
 WARR0 580648 WINDOW 200 VEPW 30 X 22 G20 T W-1020 0 111.06 0.00
 WARR0 561307 DOOR BAGGAGE SLAM LATCH ONLY W-1020 0 68.07 0.00
 WARR0 683418 BEDSPREAD 88 X 92 SIRENTE DOV W-1020 0 70.34 0.00

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 ARR01 Z992 MISC LABOUR CODE (WARR W-1020 0.00 115.00 0.00
 ARR02 Z992 MISC LABOUR CODE (WARR DL W-1020 0.50 115.00 57.50
 ARR03 Z992 MISC LABOUR CODE (WARR W-1020 0.00 115.00 0.00
 ARR04 Z992 MISC LABOUR CODE (WARR W-1020 0.00 115.00 0.00

 BILLINGS SUMMARY
 Type Bill Id Parts Labour Sublet Extras Tax Total

 W 1020 0.00 57.50 0.00 0.00 0.00 57.50
 Totals 0.00 57.50 0.00 0.00 0.00 57.50

&k2S

&k0S