

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11020

|                 |                     |                 |                   |
|-----------------|---------------------|-----------------|-------------------|
| Date In:        | 19 AUG 24           | Author:         | MZYWICKI          |
| Promised Date:  | 25 DEC 25           | Stock No:       | 11167             |
| :               | :                   | Year:           | 2024              |
| Customer Name:  | 1021 - FOREST RIVER | Manufacturer:   | FOREST RIVER      |
| Address:        | 21815 NETWORK PLACE | Brand:          | PUMA DESTINATION  |
| :               | CHICAGO, IL         | Model:          | 402LFT            |
| Postal/Zip:     | 60673-1218          | Miles/Hrs:      | 0                 |
| Phone#(res):    | 219-534-3167        | Exterior Color: | :                 |
| Phone#(bus):    | 219-534-3167        | Unit Type:      | TT-TRAVEL TRAILER |
| Cell Phone:     | :                   | License#:       | :                 |
| Email:          | NONE                | Tag#:           | :                 |
| Purchased Date: | 28 JUN 24           | :               | :                 |
| Delivery Date:  | 11 JUL 24           | :               | :                 |
| InService Date: | :                   | :               | :                 |
| Serial#:        | 4X4TPUS26RP102822   | :               | :                 |

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
1      COMPLAINT:  CUSTOMER STATES THAT THE BLIND IN THE      W      1021   FORES
          FOOT OF THE LOFT STAIRS- IN BETWEEN THE
          BEDROOM DOOR AND THE SLIDING DOOR- DOES
          NOT GO BACK UP- NEEDS TO BE REPLACED-
          CAUSE:      pics taken of shade broken internally
          CORRECTION: install new shade and tested ok
2      COMPLAINT:  CUSTOMER STATES THAT THE AWNING DOES NOT W      1021   FORES
          OPERATE CORRECTLY- CUSTOMER STATES THAT
          IT IS NOT RETRACTING PROPERLY- CUSTOMER
          STATES THAT IT IS COMING IN REALLY SLOW
          CAUSE:      taken pics for future reference
          CORRECTION: the awning is working ok normal
          operation
3      COMPLAINT:  CUSTOMER STATES THAT WHEN IT IS RAINING W      1021   FORES
          REALLY HARD, WATER GETS INTO THE FURNACE
          DOOR CAUSING THE FURNACE TO NOT OPERATE
          DUE TO IT BEING WET- NEEDS TO BE LOOKED
          AT-
          CAUSE:      correction water heater door is not
          sealing that well we could use stick on
          rubber seals to seal door for no water
          to get in
          CORRECTION: can be done in spring customer closing
          up unit install a foam seal around outer
          edge of water heater door for tight seal
          now ok
4      COMPLAINT:  CUSTOMER REQUESTS SERVICE CALL TO THEIR E      16584   PETRI
          PROPERTY 3235 CTY RD G OXFORD
*****
```

Continued on page 2

Work Order : 11020

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
      CAUSE:      CUSTOMER REQUEST
      CORRECTION: COMPLETE

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
1      82205364      SHADE ROLLER 27X72 BAMBO W-1021      1      54.59      54.59
3      711217014918 D SEAL W/TAPE BLACK .5X3 W-1021      0      0.68      0.00

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
3 WARR      MANUFACTURER WARRANTY JS W-1021      0.50      115.00      57.50
2 WARR      MANUFACTURER WARRANTY JS W-1021      0.50      115.00      57.50
1 WARR      MANUFACTURER WARRANTY JS W-1021      0.50      115.00      57.50
1 WARR      MANUFACTURER WARRANTY JS W-1021      0.50      115.00      57.50
3 WARR      MANUFACTURER WARRANTY JS W-1021      0.50      115.00      57.50

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
1 FRT      FREIGHT      W-1021      0.00      0.00      0.00
4 SSE      SHOP SUPPLIES - EXTERNAL E-16584      1.00      0.00      0.00
4 SC      SERVICE CALL      E-16584      45.00      3.75      168.75

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      16584      0.00      0.00      0.00      168.75      9.29      178.04
W      1021      54.59      287.50      0.00      0.00      0.00      342.09

      Totals      54.59      287.50      0.00      168.75      9.29      520.13

```

&k2S  
&k0S