



Warranty Claim Form

Date: 11/22/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT302XN8823270

Transcend 240ML

Retail Purchase Date: 9/6/2024

Work Started: 11/12/2024

Work Completed: 11/12/2024

Claim Status: Paid

Dealer Work Order #: 11135B

Unit Offline Date: 4/27/2022

Claim #: 852708

Labor: \$46.00

Parts: \$20.29

Shipping: \$12.49

Total: \$78.78

Notes: JPH 10-15-24 580011 denied LCI does not cover scratch, crack or shattered glass

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

17433 TAME FISH LAKE ROAD
AITKIN, Minnesota 56431
United States
218-851-9416

Operation Line # 1

Flat Rate Code: 690001 Blinds - R&R Blind

Fault Code: Damaged/Maintenance

Problem: Blind over stove does not operate properly.

Hours: .2

Cause: Blinds not working correctly.

Amount: 23.00

Remedy: R&R blinds

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
693138 BLIND MINI 38 X 11 BLACK METAL IMPORT	BLIND MINI 38 X 11 BLACK METAL IMPORT		1	1	20.29

Operation Line # 2

Flat Rate Code: 590046 Roof Vents - Reseal

Fault Code: Damaged/Maintenance

Problem: Fan over theater seating/dining needs band/resecuring- can see daylight.

Hours: .2

Cause: Fan over theater seating can see day light, rubber seal needs adjusting.

Amount: 23.00

Remedy: Adjusted the rubber seal to sit over vent better.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: