

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11531

Date In: 25 OCT 24 Author: MGRAY  
Promised Date: 01 NOV 24 Stock No: 10304  
: Year: 2022  
Customer Name: 16272 - HOFFMANN, JESS Manufacturer: GRAND DESIGN  
Address: 8355 STATE HIGHWAY 80 Brand: IMAGINE  
: MARSHFIELD, WI Model: 2910BH  
Postal/Zip: 54449 Miles/Hrs:  
Phone#(res): Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: 715-305-5740 License#:  
Email: JHOFFMANN79@LIVE.COM Tag#:  
Purchased Date: 11 JUN 22 :  
Delivery Date: 27 JUN 22 :  
InService Date: :  
Serial#: 573TE3426N6639508 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
RI COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF I SEP POLIC  
REPAIR IS NEEDED.  
CAUSE: Roof inspection.  
CORRECTION: Performed roof inspection. Had to  
install 1 sewer pipe vent cover. Was  
missing. Roof looks good.  
2 COMPLAINT: ENERCO/FLEX TECH QUICK DISCONNECT RECALL W 1020 GRAND  
CAUSE: Soap test quick disconnect for leaks.  
CORRECTION: No leak found.  
3 COMPLAINT: SOLERA AWNING WELD. W 1020 GRAND  
CAUSE: Check for solera weld recall.  
CORRECTION: Inspected awning fabric for weld recall.  
Recall not nessasary. No tag on fabric  
or tube.  
4 COMPLAINT: SEAL ON THE WINDOW OF THE SLIDE OUT E 16272 HOFFM  
TOWARD THE TOP PULLING OUT. LOOKS LIKE  
THE SEAL SHRUNK AND IS NOT BEING ABLE TO  
BE PUT BACK IN.  
CAUSE: Window seal install.  
CORRECTION: Installed new seal in front ods slide  
window.  
1 COMPLAINT: PUT VENT COVERS ON THE UNIT,PARTS ARE IN E 16272 HOFFM  
THE UNIT.  
CAUSE: Roof vent cover install.  
CORRECTION: Installed 4 roof vent covers. Customer  
had inside unit.

Continued on page 2

Work Order : 11531

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
4      82200110      WINDOW GLAZING SEAL BLAC E-16272      4      2.59      10.36
RI      014717401371 PLUMBING VENT CAP, BLACK I-SEP      1      5.99      5.99

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
RI Z991      PREFORM ROOF INSPECTIO TD      I-SEP      0.30      70.00      21.00
4 Z990      MISC LABOUR CODE (EXTE TD      E-16272      0.70      130.00      91.00
3 Z992      MISC LABOUR CODE (WARR TD      W-1020      0.50      115.00      57.50
2 Z992      MISC LABOUR CODE (WARR TD      W-1020      0.50      115.00      57.50
1 RV31I-13d ROOF VENTS REPLACE COV TD      E-16272      1.00      130.00      130.00

```

```

*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
RI  SSE      SHOP SUPPLIES - EXTERNAL      I-SEP      1.00      16.58      16.58

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      16272      10.36      221.00      0.00      0.00      12.74      244.10
I      SEP      5.99      21.00      0.00      16.58      0.00      43.57
W      1020      0.00      115.00      0.00      0.00      0.00      115.00

Totals      16.35      357.00      0.00      16.58      12.74      402.67

```

&k2S  
&k0S