

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11590B

Date In:	31 JAN 25	Author:	MZYWICKI
Promised Date:	04 JUL 25	Stock No:	11028
:	:	Year:	2024
Customer Name:	17262 - LEVERANCE, BRA	Manufacturer:	GRAND DESIGN
Address:	1681 BITTERSWEET DR	Brand:	REFLECTION 150 SERIES
:	RUDOLPH, WI	Model:	270BN
Postal/Zip:	54475	Miles/Hrs:	:
Phone#(res):	7155706232	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE@GMAIL.COM	Tag#:	RYAN
Purchased Date:	14 MAR 24	:	:
Delivery Date:	15 APR 24	:	:
InService Date:	:	:	:
Serial#:	573FR3126R3348424	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 2 - CUSTOMER STATES THE	W	1020 GRAND
		DS REAR TIRE MONITOR DOES NOT WORK PROPERLY SOMETIMES BOTH. FRONT ONE ONLY KICKS OUT ABOUT 20 MILES IN THE DRIVE- CUSTOMER STATES THAT HAPPENS AT VARIOUS TIMES- NO SET SPEED- IT TAKES ROUGHLY ABOUT TEN MILES FOR IT TO DO IT- WOULD LIKE TO HAVE DIAGNOSED-		
	CAUSE:	Follow up with Matt per CMR conversation. Unsure how to diagnose this. Typically we don't deal with TPMS systems. 1/14/25 Powered on coach, plugged in monitor for tpms, DS rear sensor would not read immediately, it eventually came on 15mins later. 1/16/25 Had powered on for an entire day, rear DS tire sensor keeps dropping connectivity and occasionally regaining connectivity as customer stated.		
	CORRECTION:	... All signs point to a dieing battery in sensor of the wheel of concern.		

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
ARR02	Z992	MISC LABOUR CODE (WARR	RW	W-1020		0.50	115.00	57.50
ARR02	WARR	MANUFACTURER WARRANTY	RW	W-1020		0.00	115.00	0.00
ARR02	WARR	MANUFACTURER WARRANTY	RW	W-1020		0.50	115.00	57.50

Continued on page 2

Work Order : 11590B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1020	0.00	115.00	0.00	0.00	0.00	115.00
	Totals	0.00	115.00	0.00	0.00	0.00	115.00

&k2S
&k0S